Ref: 7436



SOUTH AFRICAN CIVIL AVIATION AUTHORITY

ACCIDENT REPORT - EXECUTIVE SUMMARY

Aircraft Registration	ZS-IDN		Date of Accident	12/12/2001		Time of Accident		1330Z		
Type of Aircraft	CESSNA	A150K		Type of Operation		tion	n Private			
Pilot-in-command Licence Type			Private	Age	22	L	icence Valid	Yes		
Pilot-in-command Flying Experience			Total Flying Hours	150		Hours on Ty		3.6		
Last point of departure Pon			Pongola Airport							
Next point of intended landing Pon		Pongola Airport								
Location of the accident site with reference to easily defined geographical points (GPS readings if possible)										
Pongola Airport										
Meteorological Inform	ation Weather was fine									
Number of people on	board 1-	+1	No. of people in	jured	ured 0+1		No. of people kil		0	
Synopsis										

On 12 December 2001, the pilot and a passenger (his father) took off from Pongola Airport (FAPL) for a private, local flight.

After take-off they flew to the North of the field and climbed to 4000 ft in order to do aerobatic maneuvers, as the pilot's father was to demonstrate aileron rolls to the pilot. According to the passenger they did four rolls in total and on their way back to the aerodrome they did a "few" "wingovers".

Overhead the aerodrome the pilot decided to do a glide approach and joined left down wind for Runway 16. However he was too high on the approach over the threshold and initiated a go-around.

According to the pilot the engine responded well and no abnormalities were experienced. However, at a height of approximately 200 ft above ground level and abeam the hangars to the left of the runway center line, the engine stopped for a brief moment, fired again and then stopped completely.

A forced landing was carried out to the right of the runway, but prior to touch down the undercarriage contacted a metal structure and forced the aircraft into the ground, nose first.

Probable Cause

The cause for the accident was due to engine failure during the attempted go-around and the pilot being unable to clear an obstacle prior to executing a forced landing. The most probable cause for the engine failure could be attributed to fuel starvation.