

**PRELIMINARY ACCIDENT REPORT**

**Accident and Incident Investigations Division**

Accident  
- Preliminary Report -  
AIID Ref No: CA18/2/3/10450



**Figure 1:** The file picture of ZU-COB aircraft. (Source: <http://airliners.net>)

**Description:**

On Wednesday afternoon, 8 May 2024, a pilot on-board the Orion Cub aircraft with registration ZU-COB took off on a private flight from Krugersdorp Aerodrome (FAKR) in Gauteng province with the intention to return to the same aerodrome.

Upon the pilot's return to FAKR, the engine stopped after he had completed a turn; he then opted to perform a precautionary landing on the north side of the aerodrome. During the landing roll, the aircraft rolled over a trench. The aircraft was substantially damaged during the accident. The pilot was not injured.

## Occurrence Details

**Reference Number** : CA18/2/3/10450  
**Occurrence Category** : Category 2  
**Type of Operation** : Private (Part 94)  
**Name of Operator** : Avroy Shlain  
**Aircraft Registration** : ZU-COB  
**Aircraft Make and Model** : Orion Cub  
**Nationality** : South African  
**Place** : Krugersdorp Aerodrome (FAKR), Gauteng Province  
**Date and Time** : 8 May 2024 at 1445Z  
**Injuries** : None  
**Damage** : Substantial

## Purpose of the Investigation

*In terms of Regulation 12.03.1 of the Civil Aviation Regulations (CAR) 2011, this report was compiled in the interest of the promotion of aviation safety and the reduction of the risk of aviation accidents or incidents and not to apportion blame or liability.*

*All times given in this report are Co-ordinated Universal Time (UTC) and will be denoted by (Z). South African Standard Time is UTC plus 2 hours.*

## Investigation Process

The Accident and Incident Investigations Division (AIID) of the South African Civil Aviation Authority (SACAA) was notified of the occurrence which involved the Orion Cub aircraft at Krugersdorp Aerodrome, Gauteng province, on 8 May 2024 at 1445Z. The occurrence was classified as an accident according to the CAR 2011 Part 12 and the International Civil Aviation Organisation (ICAO) STD Annex 13 definitions.

The AIID has appointed an investigator-in-charge to conduct the full investigation. The investigator did not dispatch to the accident site. Notifications were sent to the State of Registry, Operator, Design and Manufacturer in accordance with the CAR 2011 Part 12 and the ICAO Annex 13 Chapter 4. The AIID will lead the investigation and issue the final report of this accident in accordance with the CAR 2011 Part 12 and the ICAO Annex 13.

The information contained in this preliminary report is derived from the information gathered during the on-going investigation into the occurrence. Later, an interim or final report may contain altered information in case new evidence is found during the on-going investigation that requires changes to the information depicted in this report.

*The AIID reports are made available to the public at:*

<https://www.caa.co.za/industry-information/accidents-and-incidents/#aircraft-accident-reports>

*Notes:*

- Whenever the following words are mentioned in this report, they shall mean the following:*  
*Accident — this investigated accident*  
*Aircraft — the Orion Cub involved in this accident*  
*Investigation — the investigation into the circumstances of this accident*  
*Pilot — the pilot involved in this accident*  
*Report — this accident report*

- 2. Photos and figures used in this report were taken from different sources and may have been adjusted from the original for the sole purpose of improving clarity of the report. Modifications to images used in this report were limited to cropping, magnification, file compression; or enhancement of colour, brightness, contrast; or addition of text boxes, arrows, or lines.*

## **Disclaimer**

This report is produced without prejudice to the rights of the AIID, which are reserved.

## Table of Contents

|   |    |
|---|----|
| Occurrence Details .....                                | 2  |
| Investigation Process.....                              | 2  |
| Disclaimer .....  | 3  |
| Contents Page .....                                     | 4  |
| Abbreviations .....                                     | 5  |
| 1. FACTUAL INFORMATION .....                            | 6  |
| 1.1. History of Flight .....                            | 6  |
| 1.2. Injuries to Persons .....                          | 7  |
| 1.3. Damage to Aircraft .....                           | 7  |
| 1.4. Other Damage .....                                 | 7  |
| 1.5. Personnel Information.....                         | 7  |
| 1.6. Aircraft Information .....                         | 8  |
| 1.7. Meteorological Information .....                   | 9  |
| 1.8. Aids to Navigation.....                            | 9  |
| 1.9. Communication .....                                | 9  |
| 1.10. Aerodrome Information .....                       | 9  |
| 1.11. Flight Recorders .....                            | 10 |
| 1.12. Wreckage and Impact Information.....              | 10 |
| 1.13. Medical and Pathological Information.....         | 10 |
| 1.14. Fire .....  | 10 |
| 1.15. Survival Aspects .....                            | 10 |
| 1.16. Tests and Research.....                           | 11 |
| 1.17. Organisational and Management Information .....   | 11 |
| 1.18. Additional Information .....                      | 11 |
| 1.19. Useful or Effective Investigation Techniques..... | 11 |
| 2. FINDINGS.....  | 11 |
| 3. ON-GOING INVESTIGATION .....                         | 12 |

| <b>Abbreviation</b> | <b>Description</b>   |
|---------------------|--|
| °                   | Degrees  |
| °C                  | Degrees Celsius  |
| A/C                 | Aircraft   |
| AIID                | Accident and Incident Investigations Division                      |
| AMSL                | Above Mean Sea Level   |
| AP                  | Approved Person  |
| ATF                 | Authority to Fly   |
| C of A              | Certificate of Airworthiness                                       |
| C of R              | Certificate of Registration  |
| CAR                 | Civil Aviation Regulations   |
| CAVOK               | Ceiling and Visibility OK  |
| CRS                 | Certificate of Release to Service                                  |
| CVR                 | Cockpit Voice Recorder   |
| FAKR                | Krugersdorp Aerodrome  |
| FDR                 | Flight Data Recorder   |
| ft                  | Feet   |
| GPS                 | Global Positioning System  |
| hPa                 | Hectopascal  |
| ICAO                | International Civil Aviation Organisation                          |
| IIC                 | Investigator-in-charge   |
| Km                  | Kilometre/s  |
| kt                  | Knot/s   |
| METAR               | Meteorological Aerodrome Report                                    |
| NPL                 | National Pilot Licence   |
| QNH                 | Query: Nautical Height   |
| RWY                 | Runway   |
| SACAA               | South African Civil Aviation Authority                             |
| SAWS                | South African Weather Service                                      |
| STOL                | Short Take Off and Landing   |
| UTC                 | Co-ordinated Universal Time  |
| VMC                 | Visual Meteorological Conditions                                   |
| Z                   | Zulu (Term for Universal Co-ordinated Time - Zero Hours Greenwich) |

## 1. FACTUAL INFORMATION

### 1.1. History of Flight

- 1.1.1. On Wednesday, 8 May 2024, a pilot on-board the Orion Cub aircraft with registration ZU-COB took off on a private flight from Krugersdorp Aerodrome (FAKR) in Gauteng province with the intention to land at the same aerodrome. Visual meteorological conditions (VMC) by day prevailed at the time of the flight which was conducted under the provisions of Part 94 of the Civil Aviation Regulations (CAR) 2011 as amended.
- 1.1.2. The pilot reported that he conducted a pre-flight inspection with no anomalies found. Thereafter, he uplifted 60 litres of Avgas 100LL into the aircraft's fuel tanks.
- 1.1.3. At approximately 1400Z, the aircraft took off from Runway 26 (RWY 26) and climbed to 6 300 feet (ft) above mean sea level (AMSL). The aircraft circled overhead the aerodrome for a few minutes before it headed north.
- 1.1.4. The pilot stated that upon his return to the aerodrome as he rolled the aircraft out of a turn, the engine stopped. He then switched on the auxiliary fuel pump and selected the individual fuel tanks, but he was unsuccessful to restart the engine. After deducing that he will not reach the aerodrome, he landed the aircraft on a farm located north of the aerodrome.
- 1.1.5. During the landing roll, the left main landing gear rolled over a trench and broke off. Moreover, one of the wooden propeller blades also broke off.
- 1.1.6. The aircraft was substantially damaged, and the pilot was not injured during the accident.
- 1.1.7. The accident occurred during daylight, approximately 2 kilometres (km) from FAKR at Global Positioning System (GPS) co-ordinates determined to be 26°07'98" South 027°72'91" East, at 5 400 feet (ft) AMSL.



**Figure 2:** The accident location. (Source: Google Earth)

## 1.2. Injuries to Persons

| Injuries     | Pilot    | Crew     | Pass.    | Total On-board | Other    |
|--------------|----------|----------|----------|----------------|----------|
| Fatal        | -        | -        | -        | -              | -        |
| Serious      | -        | -        | -        | -              | -        |
| Minor        | -        | -        | -        | -              | -        |
| None         | 1        | -        | -        | 1              | -        |
| <b>Total</b> | <b>1</b> | <b>-</b> | <b>-</b> | <b>1</b>       | <b>-</b> |

Note: Other means people on the ground.

## 1.3. Damage to Aircraft

1.3.1. The aircraft was substantially damaged.

## 1.4. Other Damage

1.4.1. None.

## 1.5. Personnel Information

|                     |                              |               |      |     |    |
|---------------------|------------------------------|---------------|------|-----|----|
| Nationality         | South African                | Gender        | Male | Age | 65 |
| Licence Type        | National Pilot Licence (NPL) |               |      |     |    |
| Licence Valid       | Yes                          | Type Endorsed | Yes  |     |    |
| Ratings             | Instruments and Night Rating |               |      |     |    |
| Medical Expiry Date | 31 August 2026               |               |      |     |    |
| Restrictions        | None                         |               |      |     |    |
| Previous Accidents  | None                         |               |      |     |    |

Note: Previous accidents refer to past accidents the pilot was involved in, when relevant to this accident.

### Flying Experience:

|                            |     |
|----------------------------|-----|
| Total Hours                | TBA |
| Total Past 24 Hours        | 1.0 |
| Total Past 7 Days          | 3.6 |
| Total Past 90 Days         | TBA |
| Total on Type Past 90 Days | TBA |
| Total on Type              | TBA |

1.5.1. The pilot was initially issued a National Pilot Licence (NPL) on 5 March 2019. His last licence validation was conducted on 6 March 2023 with an expiry date of 26 February 2025. The aircraft type was endorsed on the pilot's licence. The pilot was issued a Class 4 aviation medical certificate on 4 August 2023 with an expiry date of 31 August 2026.

1.6. **Aircraft Information** (Source: Orion Cub Manual)

1.6.1 *The Orion Cub is a high-wing tailwheel aircraft, weighing 800 kilograms (kg). It features seating for two in tandem configuration. Powered by a single Rotax 912UL turbo engine, the aircraft boasts a fuel capacity of 126 litres (L). Equipped with large, slotted flaps, it offers enhanced short take-off and landing (STOL) performance.*

**Airframe:**

|  |                   |            |
|--|-------------------|------------|
| Manufacturer/Model                         | Avroy Shlain      |            |
| Serial Number                              | 22-02             |            |
| Year of Manufacture                        | 2024              |            |
| Total Airframe Hours (At Time of Accident) | 3.6               |            |
| Last Inspection (Date & Hours)             | 17 February 2024  | 0.0        |
| Hours Since Last Inspection                | 3.6               |            |
| CRS Issue Date                             | 17 February 2024  |            |
| ATF (Issue Date & Expiry Date)             | 7 May 2024        | 6 May 2025 |
| C of R (Issue Date) (Present Owner)        | 15 February 2024  |            |
| Type of Fuel Used                          | Avgas 100LL       |            |
| Operating Category                         | Private (Part 94) |            |
| Previous Accidents                         | None              |            |

Note: Previous accidents refer to past accidents the aircraft was involved in, when relevant to this accident.

1.6.2 According to the maintenance records, the construction of the aircraft was approved by the Regulator (SACAA) on 15 March 2023 with approval number CAAD493E. The construction of the aircraft was signed off by an approved person (AP) on 17 February 2024.

1.6.3 The aircraft was first registered to the present owner on 15 February 2024. The Certificate of Release to Service (CRS) was issued by the approved person (AP) on 17 February 2024 at 0.0 airframe hours with an expiry date of 16 February 2025 or at 50 airframe hours, whichever occurs first.

1.6.4 The aircraft had a valid proving flight Authority to Fly (ATF) that was initially issued by the Regulator on 7 May 2024 with an expiry date of 6 May 2025.

1.6.5 Based on the aircraft maintenance records, the last annual inspection on the aircraft was conducted on 17 February 2024 at 0.0 airframe hours (after construction). The aircraft had accrued 3.6 airframe hours since the last inspection.

**Engine:**

|                      |                    |
|----------------------|--------------------|
| Manufacturer/Model   | Rotax 912ULS Turbo |
| Serial Number        | 10000617           |
| Hours Since New      | 3.6                |
| Hours Since Overhaul | Not Reached        |



**Propeller:**

|                      |                         |
|----------------------|-------------------------|
| Manufacturer/Model   | Ax Sport Variable Speed |
| Serial Number        | 0016                    |
| Hours Since New      | 3.6                     |
| Hours Since Overhaul | Not Reached             |

**1.7. Meteorological Information**

- 1.7.1. The weather information below was obtained from the Meteorological Aerodrome Report (METAR) that was issued by the South African Weather Service (SAWS), recorded at FAKR on 8 May 2024 at 1445Z. FAKR is located 2km from the accident site.

|                |      |             |      |            |       |
|----------------|------|-------------|------|------------|-------|
| Wind Direction | 180° | Wind Speed  | 03kt | Visibility | 9999m |
| Temperature    | 21°C | Cloud Cover | Nil  | Cloud Base | Nil   |
| Dew Point      | 16°C | QNH         | hPa  |            |       |

**1.8. Aids to Navigation**

- 1.8.1. The aircraft was equipped with standard navigational equipment as approved by the Regulator. There were no records indicating that the navigational equipment was unserviceable prior to the flight.

**1.9. Communication**

- 1.9.1. The aircraft was equipped with a standard communication system as approved by the Regulator. There were no recorded defects with the communication system prior to the flight.

**1.10. Aerodrome Information**

- 1.10.1. The accident occurred approximately 2km from FAKR.

|                           |                                |
|---------------------------|--------------------------------|
| Aerodrome Location        | Krugersdorp, Gauteng Province  |
| Aerodrome Status          | Licensed                       |
| Aerodrome GPS coordinates | 26°4'52" South, 27°43'32" East |
| Aerodrome Elevation       | 5 400ft                        |
| Runway Headings           | 8/26                           |
| Dimensions of Runway Used | 9mx818m                        |
| Heading of Runway Used    | 26                             |
| Surface of Runway Used    | Asphalt                        |
| Approach Facilities       | None                           |
| Radio Frequency           | 122.0 MHz                      |

### 1.11. Flight Recorders

1.11.1. The aircraft was neither equipped with a flight data recorder (FDR) or a cockpit voice recorder (CVR), nor was it required by regulation to be fitted to the aircraft type.

### 1.12. Wreckage and Impact Information

1.12.1. As the pilot rolled the aircraft out of a turn, the engine stopped; he attempted to restart the engine but was unsuccessful. He conducted a precautionary landing on the farm approximately 2km north of FAKR after deducing that he would not make it to the aerodrome. During the landing roll, the left main landing gear rolled over a trench and broke off. One of the wooden propeller blades broke off.



**Figure 3:** The aircraft at the accident site. (Source: Operator)

### 1.13. Medical and Pathological Information

1.13.1. None.

### 1.14. Fire

1.14.1. There was no evidence of a pre- or post-impact fire.

### 1.15. Survival Aspects

1.15.1 The accident was considered survivable as there was no damage to the cockpit and the cabin.

## 1.16. Tests and Research

1.16.1. To be discussed in the final report.

## 1.17. Organisational and Management Information

1.17.1. The flight was conducted under the provisions of Part 94 of the Civil Aviation Regulations (CAR) 2011 as amended.

1.17.2. The Regulator had inspected the aircraft after its construction on 19 April 2024.

## 1.18. Additional Information

1.18.1. To be discussed in the final report.

## 1.19. Useful or Effective Investigation Techniques

1.19.1. To be discussed in the final report.

## 2. FINDINGS

### 2.1. General

From the available evidence, the following preliminary findings were made with respect to this accident. These shall not be read as apportioning blame or liability to any organisation or individual.

To serve the objective of this investigation, the following sections are included in the conclusions heading:

- **Findings** — are statements of all significant conditions, events, or circumstances in this accident. The findings are significant steps in this accident sequence, but they are not always causal or indicate deficiencies.

### 2.2. Findings

2.2.1. The pilot was initially issued a National Pilot Licence (NPL) on 5 March 2019. His last licence validation was conducted on 6 March 2023 with an expiry date of 26 February 2025. The aircraft type was endorsed on the pilot's licence. The pilot was issued a Class 4 aviation medical certificate on 4 August 2023 with an expiry date of 31 August 2026.

2.2.2. The flight was conducted under the provisions of Part 94 of the CAR 2011 as amended.

2.2.3. The construction of the aircraft was approved by the Regulator on 15 March 2023 with approval number CAAD493E. The construction of the aircraft was signed off by an approved person on 17 February 2024.

- 2.2.4. The aircraft was first registered to the present owner on 15 February 2024. The Certificate of Release to Service (CRS) was issued by the approved person (AP) on 17 February 2024 at 0.0 airframe hours with an expiry date of 16 February 2025 or at 50 airframe hours, whichever occurs first.
- 2.2.5. The aircraft had a valid proving flight Authority to Fly (ATF) that was initially issued by the Regulator on 7 May 2024 with an expiry date of 6 May 2025.
- 2.2.6. The last annual inspection on the aircraft was conducted on 17 February 2024 at 0.0 airframe hours after construction. The aircraft had accrued 3.6 airframe hours since the last inspection.
- 2.2.7. The Regulator had inspected the aircraft after construction on 19 April 2024.
- 2.2.8 The engine stopped after the aircraft completed a turn. The pilot switched on the auxiliary fuel pump and selected individual fuel tanks but was unsuccessful to restart the engine.

### **3. ON-GOING INVESTIGATION**

- 3.1. The AIID investigation is on-going, and the investigator will investigate other aspects of this occurrence which may or may not have safety implications.

**This report is issued by:  
Accident and Incident Investigations Division  
South African Civil Aviation Authority  
Republic of South Africa**