



Section/division

Accident and Incident Investigations Division

Form Number: CA 12-12b

AIRCRAFT SERIOUS INCIDENT REPORT AND EXECUTIVE SUMMARY

				Reference:	CA18/3/2/1264	
Aircraft Registration	ZS-DFJ	Date of Incident	5 April 2019		Time of Incident	0546Z
Type of Aircraft	Dassault Aviation Falcon 900B		Type of Operation	Air Transport (Part 135)		
Pilot-in-command Licence Type	ATPL		Age	51	Licence Valid	Yes
Pilot-in-command Flying Experience	Total Flying Hours		5328		Hours on Type	1550
Last point of departure	Robert Gabriel Mugabe International Airport (FVRG), Zimbabwe					
Next point of intended landing	Victoria Falls International Airport (FVFA), Zimbabwe					
Location of the incident site with reference to easily defined geographical points (GPS readings if possible)						
50 nm South-East of FVFA (18° 33' 36" South, 026° 44' 00" East)						
Meteorological Information	Wind: 120°/8 kt, Temperature: 23°C, Dew point: 8°C, Visibility: CAVOK, QNH: 1023 hPa					
Number of people on-board	2 + 8	No. of people injured	0	No. of people killed	0	
Synopsis						
<p>On Friday, 5 April 2019, at 0509Z, a Dassault Aviation Falcon 900B, with registration markings ZS-DFJ, departed Robert Gabriel Mugabe International Airport (FVRG) in Harare, Zimbabwe, on an unscheduled charter flight to Victoria Falls International Airport (FVFA) in Zimbabwe. On-board the aircraft were two crew members and eight passengers.</p> <p>The aircraft reached a cruising altitude of 38 000 feet (FL380) en-route to FVFA. At approximately 60 nautical miles (nm) from FVFA, the crew commenced with the descent. While passing through FL250, the pilot-in-command, who was seated on the left seat, reported that his Electronic Horizontal Situation Indicator (EHSI), Electronic Attitude Direction Indicator (EADI) and Multi-Function Display (MFD) started to blink and then went blank. This was followed by various warning lights on the "master caution" panel. Shortly after this, the First Officer (FO) noticed smoke entering the flight deck through the roof lining above the right-hand flight deck window. The flight crew immediately donned their oxygen masks and carried out the necessary checklists from the aircraft flight manual (AFM) regarding electrical smoke or fire. The FO declared an emergency and broadcasted a Mayday call to FVFA tower frequency. The aircraft was given priority and cleared for a straight-in approach for Runway 30. The crew expedited the descent and, while passing FL190, the smoke began to dissipate. When passing through FL140, the crew removed their oxygen masks and prepared the aircraft for the approach. The FVFA Aircraft Rescue and Fire-Fighting (ARFF) services were ready for the aircraft and positioned themselves next to the runway. The aircraft landed safely at 0602Z and taxied to the apron where the occupants disembarked normally. The aircraft sustained damage to a wiring loom that had burnt in the ceiling of the flight deck, as well as excessive heat damage to a ceiling panel above the wire loom. The operator had done a modification by installing an automatic dependent surveillance-broadcast (ADS-B) system on 30 August 2018 and that required an additional wire to be added to the loom routing to the circuit breaker panel. The last maintenance conducted in this area of the burnt loom was during the last C check on 8 November 2018 which was a visual inspection. None of the occupants sustained any injuries during the incident sequence.</p> <p>The investigation revealed that during the modification which required cable be threaded on to the wiring loom secured by a clamp, it is likely that when the wire was threaded through the clamp, the wire insulation was inadvertently damaged due to the clamp not being opened, and the open damaged wire started to arc on the clamp causing high temperature which resulted on the smoke in the flight deck, multiple system failure.</p>						
SRP Date	12 November 2019		Publication Date	18 November 2019		

TABLE OF CONTENTS	PAGE NO.
List of Abbreviations and Definitions	3
1. FACTUAL INFORMATION	5
1.1 History of Flight	5
1.2 Injuries to Persons	7
1.3 Damage to Aircraft	7
1.4 Other Damage	9
1.5 Personnel Information	9
1.6 Aircraft Information	11
1.7 Meteorological Information	12
1.8 Aids to Navigation	12
1.9 Communication	13
1.10 Airport Information	13
1.11 Flight Recorders	14
1.12 Wreckage and Impact Information	14
1.13 Medical and Pathological Information	14
1.14 Fire	15
1.15 Survival Aspects	15
1.16 Tests and Research	15
1.17 Organisational and Management Information	18
1.18 Additional Information	19
1.19 Useful or Effective Investigation Techniques	19
2. ANALYSIS	19
2.1 General	19
3. CONCLUSION	20
3.1 General	20
3.2 Findings	21
3.3 Probable Cause	22
3.4 Contributing Factors	22
4. SAFETY RECOMMENDATIONS	22
4.1 General	22
5. APPENDICES	23
5.1 Appendix A (Airplane Flight Manual Procedures: Air Conditioning Smoke)	24
5.2 Appendix B (Airplane Flight Manual Procedures: Electrical Smoke or Fire)	25
5.3 Appendix C (Airplane Flight Manual Procedures: Smoke and unusual odor removal)	27
5.4 Appendix D (Aeronautical Information Circular 023-2017)	28
5.5 Appendix E (Systems Affected by The Damaged Loom)	30
5.6 Appendix F (ICAO ARFF categories)	33
5.7 Appendix G (MEL Extract for Reversion Controller Panel)	37
5.8 Appendix H (EFIS layout)	38
5.9 Appendix I (Supplemental Type Certificate)	39
5.9 Appendix J (STC embodiment procedure)	40
5.9 Appendix K (Electrical Load Analysis)	43

ABBREVIATION	DESCRIPTION
AFM	Aircraft Flight Manual
AMM	Aircraft Maintenance Manual
AMSL	Above Mean Sea Level
ARFF	Aircraft Rescue and Fire-Fighting
ATPL	Airline Transport Pilot Licence
CAAZ	Civil Aviation Authority of Zimbabwe
CAVOK	Ceiling and Visibility OK
C of A	Certificate of Airworthiness
C of R	Certificate of Registration
DME	Distance Measuring Equipment
EADI	Electronic Attitude Direction Indicator
EHSI	Electronic Horizontal Situation Indicator
FALA	Lanseria International Airport
FL	Flight Level (Standard Air Pressure, Expressed in Hundreds Of Feet)
FO	First Officer
FVFA	Victoria Falls International Airport, Zimbabwe
FVRG	Robert Gabriel Mugabe International Airport (Harare), Zimbabwe
ft	Feet
GP	Ground Proximity
hPa	hectopascal
kt	Knot
ICAO	International Civil Aviation Organization
IFR	Instrument Flying Rules
IIC	Investigator-in-Charge
MFD	Multi-Function Display
MHz	Megahertz
NM	Nautical Mile
PAPI	Precision Approach Path Indicator
PIC	Pilot-In-Command
QNH	Query: Nautical Height
SACAR	South African Civil Aviation Regulations, 2011
SACAT	South African Civil Aviation Technical Standards, 2011
SAWS	South African Weather Service
STC	Supplemental Type Certificate
VHF	Very High Frequency
Z	Zulu (Term for Universal Coordinated Time - Zero Hours Greenwich)

Reference Number : CA18/3/2/1264
Name of Owner : Cirano Investments 307 (Pty) Ltd
Name of Operator : Zenith Air CC
Manufacturer : Dassault Aviation
Model : Falcon 900B
Nationality : South African
Registration markings : ZS-DFJ
Place : En-route to Victoria Falls Airport (FVFA), Zimbabwe
Date : 5 April 2019
Time : 0546Z

All times given in this report are Co-ordinated Universal Time (UTC) and will be denoted by (Z). South African Standard Time is UTC plus 2 hours.

Purpose of the Investigation:

*In terms of Regulation 12.03.1 of the Civil Aviation Regulations (CAR) 2011, this report was compiled in the interest of the promotion of aviation safety and the reduction of the risk of aviation accidents or incidents and **not to apportion blame or liability.***

Investigations process:

The Accident and Incident Investigations Division (AIID) of the South African Civil Aviation Authority (SACAA) was informed about an aircraft incident involving a Dassault Aviation Falcon 900B, which occurred during the descent into Victoria Falls Airport on 5 April 2019. This serious incident was delegated to the AIID on 30 April 2019 by the Civil Aviation Authority of Zimbabwe (CAAZ) as per the provisions contained in the International Civil Aviation Organisation (ICAO) Annex 13, Chapter 5, paragraph 5.1.2.

The AIID appointed an investigator-in-charge (IIC) with an investigation team (Team). The (CAAZ had sent notifications to the State of Registry, State of Operator and the State of Manufacture and Design. The Bureau d'Enquêtes et d'Analyses pour la Sécurité de l'Aviation Civile (BEA) of France that is representing the State of Manufacture has nominated an accredited representative. The AIID will lead the investigation and issue the Final Report.

Notes:

1. *Whenever the following words are mentioned in this Report, they shall mean the following:*

- *Incident — this investigated incident;*
- *Aircraft — the Dassault Aviation Falcon 900B involved in this incident;*
- *Investigation — the investigation into the circumstances of this incident;*
- *Pilot — the pilot/s involved in this incident;*
- *Report — this incident report.*

2. *Photos and figures used in this report are taken from different sources and may be adjusted from the original for the sole purpose of improving the clarity of the report. Modifications to images used in this report are limited to cropping, magnification, file compression or enhancement of colour, brightness, contrast or addition of text boxes, arrows or lines.*

Disclaimer:

This report is produced without prejudice to the rights of the SACAA, which are reserved.

1. FACTUAL INFORMATION

1.1 History of Flight

- 1.1.1 On Friday, 5 April 2019, at 0509Z, a Dassault Aviation Falcon 900B with registration markings ZS-DFJ, departed Robert Gabriel Mugabe International Airport (FVRG) in Harare, Zimbabwe, on an unscheduled charter flight to Victoria Falls International Airport (FVFA), Zimbabwe. On-board the aircraft were two crew members and eight passengers. The flight was carried out in accordance with Air Transport Operations (Part 135) of the Civil Aviation Regulations (CAR), 2011.
- 1.1.2 The aircraft reached a cruising altitude of 38 000 feet (ft.) (FL380) en-route to FVFA. Approximately 60 nautical miles (nm) from FVFA, the crew commenced with the descent. While passing FL250, the pilot-in-Command (PIC) who was seated on the left seat reported that his Electronic Horizontal Situation Indicator (EHSI), Electronic Attitude Direction Indicator (EADI) and Multi-Function Display (MFD) initially started to blink and then went blank. This was followed by various warnings on the “master caution” panel. Shortly after this, the First Officer (FO) noticed smoke entering the flight deck from the ceiling panel above the right-hand flight deck window.
- 1.1.3 The flight crew immediately donned their oxygen masks and carried out the necessary checklists from the Airplane Flying Manual (AFM) regarding electrical smoke or fire. The FO declared an emergency and broadcasted a Mayday call to the FVFA tower, which gave landing priority to the aircraft and cleared it for a straight-in approach for Runway 30.
- 1.1.4 The crew expedited the descent and, while passing FL190, the smoke began to dissipate. After passing FL140, the crew removed their oxygen masks and prepared the aircraft for the approach. The Airport Rescue and Fire-Fighting (ARFF) services at FVFA were placed on standby and were positioned next to the runway. The aircraft landed safely at 0602Z using Runway 30 and taxied to the apron where occupants disembarked normally. The total flight time was 53 minutes.
- 1.1.5 The aircraft sustained damage to a wire loom (various electrical conducting wires which are insulated and bound together), which had burnt in the ceiling of the flight deck, as well as burn damage to the ceiling panel above the wire loom. The duration from the first sighting of smoke to the time it began to dissipate was approximately 3 minutes.
- 1.1.6 None of the occupants sustained any injuries during the incident sequence.
- 1.1.7 The flight was conducted under Instrument Flying Rules (IFR) by day with fine weather conditions prevailing at the time.



Figure 1: The ZS-DFJ aircraft. (Source: Jetphotos.com/Wesley Moolman)




Figure 2: The flight routing from FVRG to FVFA. (Source: Skyvector)




Figure 3: The approximate location of the incident 50nm south-east of FVFA. (Source: Skyvector)

1.2 Injuries to Persons

Injuries	Pilot	Crew	Pass.	Other
Fatal	-	-	-	-
Serious	-	-	-	-
Minor	-	-	-	-
None	2	-	8	-

1.2.1 Seven passengers were Zimbabweans and one passenger was a South African. The two crew members were also South Africans

1.3 Damage to Aircraft

1.3.1 The aircraft sustained minor damage to an overhead panel located between frame 4 and 5 which showed signs of burning. The loom had run directly below this panel. The burn damage to the loom was limited to an area near a mounting clamp which had failed.




Figure 4: Location of the burnt ceiling panel and position of the burnt loom. (Source: Dassault Aviation)



Figure 5: Burn damage sustained to the ceiling panel. (Source: Zenith Aviation)




Figure 6: Burn damage sustained to the wire loom (Source: Zenith Aviation)

1.4 Other Damage

1.4.1 None.

1.5 Personnel Information

1.5.1 On 4 April 2019, the day preceding the incident flight, both crew members flew a total of 1.3 hours on a flight from Lanseria International Airport (FALA) to FVRG. The flight arrived at FVRG at 2016Z.

1.5.2 The incident flight was the first flight of the day and had departed FVRG for FVFA at 0509Z.

1.5.3 The PIC was seated on the left seat and the FO was seated on the right seat.

1.5.4 Pilot-in-command

Nationality	South African	Gender	Male	Age	51
Licence number	*****	Licence type	Airline Transport Pilot		
Licence valid	Yes	Type endorsed	Yes		
Ratings	Instrument, Night				
Medical expiry date	31 May 2020				
Restrictions	Corrective lenses				
Previous incident	None				

- 1.5.5 The PIC was the holder of a valid class 1 aviation medical certificate, which was issued on 14 May 2019 with an expiry date of 31 May 2020.

Flying experience:

Total hours	5 328
Total past 90 days	103
Total on type past 90 days	103
Total on type	1 550

- 1.5.6 First Officer

Nationality	South African	Gender	Male	Age	48
Licence number	*****	Licence type	Airline Transport Pilot		
Licence valid	Yes	Type endorsed	Yes		
Ratings	Instrument, Night, Test Pilot (Class 2), RNP-APCH				
Medical expiry date	30 April 2020				
Restrictions	Corrective lenses				
Previous incidents	None				

- 1.5.7 The FO was the holder of a valid class 1 aviation medical certificate, which was issued on 11 April 2019 with an expiry of 30 April 2020.

Flying experience:

Total hours	8 342
Total past 90 days	140
Total on type past 90 days	103
Total on type	201

- 1.5.8 Aircraft Maintenance Engineer

Nationality	South African	Gender	Male	Age	29
Licence number	*****	Licence type	Aircraft Maintenance Engineer		
Licence valid	Yes	Type endorsed	Yes		
Ratings	Category W, X				

- 1.5.9 Aircraft Maintenance Engineer (dual inspector)

Nationality	South African	Gender	Male	Age	34
Licence number	*****	Licence type	Aircraft Maintenance Engineer		
Licence valid	Yes	Type endorsed	Yes		
Ratings	Category A, C				

- 1.5.10 The Civil Aviation Regulations, Part 67 (Medical Certification) does not stipulate that an aircraft maintenance engineer (AME) needs to carry out or maintain a valid aviation medical certificate.

1.6 Aircraft Information

Airframe

Type	Falcon 900B	
Serial number	141	
Manufacturer	Dassault Aviation	
Year of manufacture	1994	
Total airframe hours (at time of incident)	5 211.9	
Last scheduled inspection (hours & date)	5 094.8	8 November 2018
Hours since last inspection (C Check)	117.1	
C of A (issue date)	10 December 2018	
C of A (expiry date)	9 December 2019	
C of R (issue date) (Present owner)	2 May 2018	
Operating categories	Standard Transport	

- 1.6.1 On 30 August 2018, a single wire was threaded through the failed clamp without loosening the clamp during a modification embodiment. This wire linked the ADS-B system to its associated circuit breaker. According to the operator, a dual inspection was carried out on completion of the modification.
- 1.6.2 The last maintenance conducted in the area of the burnt loom was during the last C check on 8 November 2018. This was a visual inspection.
- 1.6.3 The aircraft was last refuelled at FALA on 4 April 2019. A total of 7016lbs of Jet A-1 fuel was uplifted. On arrival at FVFA, the aircraft had 1116 lbs of fuel remaining on-board.
- 1.6.4 During preparation for departure from FALA to FVRG on 4 April 2019, the flying crew noticed that the right reversion controller panel was unserviceable. After carrying out troubleshooting, it was decided that the aircraft would be dispatched with the right reversion controller panel inoperative. This dispatch was done according to the limitations of the Minimum Equipment List (MEL) which required operation not to exceed 10 calendar days from midnight on the day of dispatch. According to the MEL, the reversion controller panel had to be replaced before 15 April 2019 (refer to Appendix G).
- 1.6.5 The reversion controller panel allows the pilot to interact with the Electronic Flight Information System (EFIS) by using the inertial reference system, selecting between indicated airspeed and Mach number and selecting between the horizontal situation indicator and the attitude director indicator. Refer to Appendix H for the EFIS layout.

Engine No. 1

Type	Honeywell
Part number	TPE731-5BR-1C
Serial number	P-101226
Hours since new	5 126.1
Hours since overhaul	3 046.2

Engine No. 2

Type	Honeywell
Part number	TPE731-5BR-1C
Serial number	P-101228
Hours since new	5 056.8
Hours since overhaul	2 976.9

Engine No. 3

Type	Honeywell
Part number	TPE731-5BR-1C
Serial number	P-101235
Hours since new	5 126.1
Hours since overhaul	2046.2

1.7 Meteorological Information

- 1.7.1 The pilots received their briefing from the South African Weather Service SAWS prior to departing for FVFA on the morning of the incident flight.

Wind direction	120°	Wind speed	8 kt	Visibility	CAVOK
Temperature	23°C	Cloud cover	Nil	Cloud base	Nil
Dew point	8°C	QNH	1023 hPa		

- 1.7.2 The flight was conducted during day light conditions with fine weather prevailing for the duration of the flight.

1.8 Aids to navigation

- 1.8.1 The aircraft was dispatched with the right-hand reversion controller panel being inoperative. Due to the right-hand reversion controller panel being inoperative, the crew were reliant on the left-hand navigation display for guidance. The crew lost all navigation displays due to the damage caused by the burnt wires and the aircraft carried out a visual approach to land at FVFA.
- 1.8.2 Records show that on 30 August 2018, the aircraft was modified with a Global Positioning System/Wide Area Augmentation system to ensure the aircraft was Automatic Dependent Surveillance – Broadcast (ADS-B) compliant. The installation was carried out in accordance with the Supplemental Type Certificate (STC) number: ST02970NY (Refer to Appendix H). The system was fitted, tested and found serviceable. The requirement to carry out the South African Civil Aviation (SACAA) mandated modification is listed in the Aeronautical Information Circular 023-2017 (See Appendix D). To accomplish the above modification, the wire for the ADS-B system was threaded through the clamp without loosening the clamp. The

modification was carried out by an approved aircraft maintenance organisation (AMO) at FALA.

1.8.2.1 Due to the fact that the CoA was not revoked during modification and the Weight and Balance (W&B) was not changed, SACAA regards the modification as minor and thus not requiring any approval only submission of documents for filing.

1.8.3 Skybrary

[https://www.skybrary.aero/index.php/Automatic_Dependent_Surveillance_Broadcast_\(ADS-B\)](https://www.skybrary.aero/index.php/Automatic_Dependent_Surveillance_Broadcast_(ADS-B)) defines ADS-B as: “ADS-B is a Surveillance technique that relies on aircraft or airport vehicles broadcasting their identity, position and other information derived from on board systems (Global Navigation Satellite System etc.). This signal (ADS-B Out) can be captured for surveillance purposes on the ground (ADS-B Out) or on-board other aircraft in order to facilitate airborne traffic situational awareness, spacing, separation and self-separation (ADS-B In). ADS-B is automatic because no external stimulus is required; it is dependent because it relies on on-board systems to provide surveillance information to other parties. Finally, the data is broadcast, the originating source has no knowledge of who receives the data and there is no interrogation or two-way contract.”

1.9 Communication

1.9.1 The aircraft was equipped with standard communication equipment as per the minimum equipment list approved by the Regulator (SACAA). There were no recorded defects prior to the incident.

1.9.2 The aircraft was in contact with FVFA approach at the time of the incident and a Mayday call was broadcasted to this station on frequency 121.1 megahertz (MHz).

1.10 Airport Information

Airport location	Victoria Falls, Zimbabwe
Airport co-ordinates	18°06'06.36" South 025°50'55.02" East
Airport elevation	3 494 ft AMSL
Runway designations	12/30
Runway dimensions	4 000 x 45m
Runway used	30
Runway surface	Asphalt
Approach facilities	PAPI, Runway lights
Airport status	Licensed

1.10.1 The aircraft carried out a visual approach to land using Runway 30. The runway is 4000m long and 45m wide. It has a prepared asphalt surface. Runway 30 has Precision Approach Path Indicator (PAPI) lights installed.

1.10.2 FVFA ARFF is rated at category 7 (refer to appendix F). The ARFF were placed on standby and escorted the aircraft to the apron.



Figure 7: FVFA Airport layout (Source: Google Earth)

1.11 Flight Recorders

1.11.1 The aircraft was fitted with an L3 Technologies cockpit voice recorder (CVR). The part number for the CVR was: 2100-1025-22 and the serial number was: 001205828. The CVR was downloaded by the same service provider who downloaded the FDR at FALA. The CVR had a recording time of 2 hours, however the CVR recordings for the incident flight were not available as the data had been overwritten.

1.11.2 The aircraft was fitted with an L3 Technologies solid state Flight Data Recorder (FDR). The part number for the FDR was: 2100-4043-00 and the serial number was: 001203248. The recording was downloaded after the incident by the service provider at FALA.

1.12 Wreckage and Impact Information

1.12.1 Not applicable.

1.13 Medical and pathological information

1.13.1 None.

1.14 Fire

- 1.14.1 There was no evidence of a pre- or post-impact fire, however, there was smoke in the flight deck area during the descent into FVFA. The cause of the smoke was due to a wire loom overheating and melting the insulation around it. Due to the excessive heat generated, one ceiling panel above the loom showed signs of excessive heat damage, and it was the source of the smoke which entered the flight deck.
- 1.14.2 The smoke entered the flight deck as the aircraft was passing through FL250 on the descent. After carrying out the required AFM steps, the smoke began dissipating as the aircraft passed FL190 before clearing.
- 1.14.3 The ARFF at FVFA had been placed on standby and escorted the aircraft to the apron. The smoke did not affect the evacuation process and the occupants disembarked normally.

1.15 Survival aspects

- 1.15.1 The incident was considered survivable as the aircraft never lost control as a result of the damaged loom and it landed safely at FVFA. The smoke began dissipating after the crew carried out the required AFM checklists.

1.16 Tests and Research

- 1.16.1 The remains of the wiring loom repair were sent to Dassault Aviation for analysis. Due to the condition of the remnants, Dassault Aviation were unable to carry out any testing to determine the integrity of the wires.



Figure 9: The wire off cuts sent to Dassault Aviation after the temporary repair was carried out. (Source: Dassault Aviation)

- 1.16.2 The operator had received the aircraft with clamp already installed. The last visual inspection of the area was carried out in 8 November 2018. The Supplemental Type

Certificate (STC) requires the AME who is embodying the modification to refer to the Dassault Falcon 900B Aircraft Maintenance Manual (AMM) when further information is required about the aircraft wiring that is related to the modification. The AMM for this aircraft does not state that a clamp is required to be opened when inserting a wire through it. See appendix J.

1.16.3 The clamp is made up of a steel loop covered with a silicone cushion.




Figure 10: The failed clamp (Source: Zenith Air)

1.16.5 The wire loom routed above the ceiling to an overhead circuit breaker panel. As the wire loom started heating up, the circuit breakers began tripping, causing the circuits of each wire in the loom to be disconnected from its associated system. This is a protection feature to prevent excessive current conditions from damaging the aircraft and its systems. The tripping of the circuit breakers also led to multiple systems failure, such as the PIC's display going off-line.




Figure 11: Location of the wire loom and circuit breaker panel.

1.16.6 The Civil Aviation Authority of New Zealand's Vector magazine of December 2001 defines a circuit breaker as "*A Circuit Protection Device (CPD) is used to protect electrical/electronic circuit components from an over-voltage or overcurrent condition, by automatically interrupting the current flow. The most common types of CPD's used in aircraft are the circuit breaker and the fuse. They are designed to interrupt the flow of electrical current when specific conditions of time and current are reached. Those conditions generate heat, and circuit breakers are designed to trip (open the circuit) before this heat damages either wiring. A specification might be for a breaker to trip under a massive short jolt (eg, 10 times the rated load of the circuit breaker for between .5 to 1.4 seconds) or a longer, less intense overload (eg, twice the rated amperage for 3–130 seconds, depending on the type of circuit breaker). If the designed overload conditions are not exceeded, the circuit breaker will not trip. The very tolerances that must be built into a circuit breaker to prevent nuisance tripping, such as the high transient current that flows when a motor or component is started, mean some glitches may not trip the breaker.*"

1.16.7 With reference to Figure 12, during normal operation, the thermal element remains in place and the latch mechanism holds the button in place. This keeps the current flowing through the circuit. If an overheat condition occurs, the thermal element expands, which then pulls back the latch mechanism and the spring-loaded button pops out. This causes a break in the circuit, essentially switching the system off.




Figure 12: A typical aircraft circuit breaker. (Source: <http://www.industrial-electronics.com>)

1.16.8 The last electrical load analysis was carried out by AMO on 08 November 2018 at 5094.8 airframe hours and the AMO concluded that the electrical load values for each item reflect the manufacturers specification. See appendix K.

1.17 Organisational and Management Information

1.17.1 The operator had been issued with an international air service licence on 11 November 2010 and was also issued with an Air Operator Certificate (AOC) on 6 June 2018 with an expiry date of 31 May 2019.

1.17.2 The aircraft maintenance organisation (AMO) number 1230 had been issued with a Part 145 Approval certificate on 21 May 2018 with an expiry date of 31 May 2019.

1.17.3 The AMO number 0198, which incorporated the STC in November 2018, had been issued with an Approval certificate on 4 October 2018 with an expiry date of 31 October 2019.

1.18 Additional Information

- 1.18.1 Physlink.com (<https://www.physlink.com/education/askexperts/ae470.cfm>) defines a short circuit as “A short circuit is simply a low resistance connection between the two conductors supplying electrical power to any circuit. This results in excessive current flow in the power source through the 'short,' and may even cause the power source to be destroyed. If a fuse is in the supply circuit, it will do its job and blow out, opening the circuit and stopping the current flow. A short circuit may be in a direct- or alternating-current (DC or AC) circuit. Short circuits can produce very high temperatures due to the high-power dissipation in the circuit.” While Circuit Globe defines a short circuit as “The circuit that allows the electric current to pass through the random path which has low resistance is known as the short circuit. The short circuit causes the heavy current which damages the insulation of the electrical equipment. It mainly occurs when the two wire touches each other or when the insulation between the conductor breaks down.”
- 1.18.2 By considering the above definitions, if the integrity of the insulation of two adjacent wires in the wire loom were compromised, an excessive heating effect would take place. This added heating would affect the integrity of the remaining wires in the loom, causing a further increase in heating as more wires short circuit.

1.19 Useful or Effective Investigation Techniques

- 1.19.1 None.

2. ANALYSIS

From the evidence available, the following analysis was made with respect to this incident. These shall not be read as apportioning blame or liability to any organisation or individual.

- 2.1 The PIC had been issued with an airline transport pilot licence (ATPL) with the required rating to operate the aircraft. The PIC accumulated a total of 1550 hours on the Falcon 900 and also had a total of 5328 flying hours. The PIC had been issued with an aviation medical certificate with the limitation to wear corrective lenses.
- 2.2 The FO had been issued with an airline transport pilot licence (ATPL) with the required rating to operate the aircraft. The FO accumulated a total of 201 hours on the Falcon 900 and also had a total of 8342 flying hours. The FO had been issued with an aviation medical certificate with the limitation to wear corrective lenses.
- 2.3 The aircraft had been issued with a certificate of airworthiness (CoA) which was within its time limits and a certificate of registration (CoR).
- 2.4 The last major inspection was a C check which was carried out on 8 November 2018 at 5 094.8 airframe hours and the aircraft had flown a further 117.1 hours since its last inspection.

- 2.5 The weather at the time of the incident was visual meteorological condition (VMC) with no reports of any significant conditions that may have adversely affected the operation of the aircraft. Although the weather was VMC, the aircraft was operating under radar control and was required to operate under Instrument Flying Rules (IFR)
- 2.6 The operator had been issued with an operating certificate which allowed the operator to carry out commercial air transport operations.
- 2.7 The AMO which maintained the aircraft had been issued with a maintenance approval which allowed the AMO to maintain the aircraft.
- 2.8 The aircraft was in a descent and passing FL250 when the PIC's instruments failed, and smoke entered the flight deck. The crew donned their oxygen masks and carried out the required AFM steps. The smoke began to dissipate as the aircraft was passing through FL190. The aircraft landed safely on Runway 30 at FVFA.
- 2.9 FVFA is a licensed-manned Airport. The runway is a prepared asphalt with a length of 4000 metres (m) and a width of 45m. The ARFF rated at category 7 were placed on standby and escorted the aircraft as it was taxiing to the apron.
- 2.10 On 30 August 2018, a modification was embodied to ensure the aircraft is ADS-B compliant. The modification required that a single wire be added to the wire loom. The wire was routed through the clamp (without the clamp being opened); and the wire was threaded through it (the clamp). The aircraft standard practices manual does not state that a clamp should be opened when adding an additional wire to a loom. The last maintenance conducted in this area of the burnt loom was during the last C check on 8 November 2018 which was a visual inspection.
- 2.11 The investigation revealed that there had been a modification which required that a cable be threaded on to the wiring loom which is secured by clamps to the airframe. During the threading of the cable, the securing clamp was not opened, and it is likely that when the wire was threaded through the clamp, the insulation was inadvertently compromised, and the open wire started to arc on the clamp. That in turn caused the increase in temperature which compromised the other wires, resulting in the smoke in the flight deck, as well as multiple systems failure.

3. CONCLUSION

3.1 General

From the evidence available, the following findings, causes and contributing factors were made with respect to this incident. These shall not be read as apportioning blame or liability to any organisation or individual.

To serve the objective of this investigation, the following sections are included in the conclusions heading:

- **Findings** — are statements of all significant conditions, events or circumstances in this incident. The findings are significant steps in this incident sequence, but they are not always causal or indicate deficiencies.

- **Causes** — are actions, omissions, events, conditions or a combination thereof, which led to this incident.
- **Contributing factors** — are actions, omissions, events, conditions or a combination thereof, which, if eliminated, avoided or absent, would have reduced the probability of the accident or incident occurring, or mitigated the severity of the consequences of the incident. The identification of contributing factors does not imply the assignment of fault or the determination of administrative, civil or criminal liability.

3.2 Findings

- 3.2.1 The PIC had been initially issued an airline transport pilot licence (ATPL) on 14 December 1998 and, after his last skills test which was carried out on 18 February 2019, he had been issued a renewal with an expiry date of 29 February 2020. The PIC held the necessary ratings to operate the aircraft and had flown a total 1 550 hours on type. The PIC had also been issued with a class 1 aviation medical certificate on 14 May 2019 with an expiry date of 31 May 2020 and his certificate was issued with a limitation to wear corrective lenses.
- 3.2.2 The FO had been issued with an airline transport pilot licence (ATP) on 30 September 2003 with an expiry date of 29 February 2020. His last skills test was carried out on 18 February 2019 and due to expire on 29 February 2020. The FO had the necessary ratings to operate the aircraft and had flown a total 201 hours on type. The FO had been issued with a class 1 aviation medical certificate on 11 May 2019 with an expiry date of 30 April 2020 and his certificate was issued with a limitation to wear corrective lenses.
- 3.2.3 The aircraft had been issued with a certificate of airworthiness on 10 December 2018 with an expiry date of 31 December 2019.
- 3.2.4 The last scheduled maintenance check that was carried out on the aircraft prior to the incident flight was a C check that was certified on 8 November 2018 at 5 094.8 airframe hours. The aircraft had accumulated an additional 117.1 airframe hours since the last inspection.
- 3.2.5 The aircraft had been modified on 30 August 2018, to ensure it was ADS-B compliant. During this process, a wire from the system was added to the loom and routed through the clamp (without the clamp being opened); and the wire was threaded through it (the clamp). The aircraft had flown a total of 151.3 hours and carried out 117 cycles since the modification was embodied. The last maintenance conducted in this area of the burnt loom was during the last C check on 8 November 2018 which was a visual inspection.
- 3.2.6 Although the weather was VMC, the crew were required to operate under IFR as they were under radar control. The weather did not play a role in the incident and fine weather conditions prevailed.

- 3.2.7 After this incident, the aircraft had undergone a temporary repair under the supervision of the Civil Aviation Authority of Zimbabwe (CAAZ) on 6 and 7 April 2019 and was ferried back to its base in South Africa, which is in FALA on 8 April 2019.
- 3.2.8 The CVR had a recording time of 2 hours, however the CVR recordings for the incident flight were not available as the data had been overwritten. The CVR download was considered to be irrelevant to the investigation.
- 3.2.9 The aircraft sustained damage to the wire loom and the flight deck ceiling panel. The crew and passengers were not injured during the incident sequence.
- 3.2.10 The investigation revealed that there had been a modification which required that a cable be threaded on to the wiring loom which is secured by clamps to the airframe. During the threading of the cable, the securing clamp was not opened, and it is likely that when the wire was threaded through the clamp, the wire insulation was inadvertently damaged, and the open wire started to arc on the clamp. That in turn caused the increase in temperature which resulted in the smoke in the flight deck, as well as multiple systems failure.

3.3 Probable Cause

- 3.3.1 During the modification which required cable be threaded on to the wiring loom secured by a clamp, it is likely that when the wire was threaded through the clamp, the wire insulation was inadvertently damaged due to the clamp not being opened, and the damaged wire started to arc on the clamp causing high temperature which resulted on the smoke in the flight deck, multiple system failure.

3.4 Contributory Factors:

- 3.4.1 Wiring clamp not opened during the threading of the wire on to the wiring loom.

4. SAFETY RECOMMENDATIONS

4.1 General

The safety recommendations listed in this report are proposed according to paragraph 6.8 of Annex 13 to the Convention on International Civil Aviation and are based on the conclusions listed in heading 3 of this report; the AIID expects that all safety issues identified by the investigation are addressed by the receiving States and organisations.

4.2 Safety Recommendation/s

- 4.2.1 None.

5. APPENDICES

- Appendix A (Airplane Flight Manual Procedures: Air Conditioning Smoke)
- Appendix B (Airplane Flight Manual Procedures: Electrical Smoke or Fire)
- Appendix C (Airplane Flight Manual Procedures: Smoke and unusual odour removal)
- Appendix D (Aeronautical Information Circular 023-2017)
- Appendix E (Systems Affected by The Damaged Loom)
- Appendix F (ICAO ARFF categories)
- Appendix G (MEL Extract for Reversion Controller Panel)
- Appendix H (EFIS layout)
- Appendix I (Supplemental Type Certificate)
- Appendix J (STC embodiment procedure)
- Appendix K (Electrical Load Analysis)

Appendix A


MYSTERE-FALCON 900
AIRPLANE FLIGHT MANUAL

EMERGENCY PROCEDURES

AIR CONDITIONING SMOKE



WARNING – Smoke at air conditioning outlets

– or **AFT LAV SMOKE** light on (modification M2325 complied with).

PHASE 1

- Crew oxygen masks Donned – 100 % + EMERGENCY
- Smoke goggles Donned – Vent valve open
- Microphone selector MASK – Tested
-  light pushbutton On
- PASSENGER OXYGEN controller OVERRIDE
 - Passenger masks Donned – Checked

PHASE 2

- Crew air gaspers Open
- Isolation valve knob ISOLATION
 - **ISOL** light On
- Bleed air CREW switch OFF
- COND control lever (A/C SN < 163) TIED
- Crossfeed valve (A/C SN ≥ 163) Open

_____ If smoke persists:

- Bleed air CREW switch ON
- Bleed air PASSENGER switch OFF

_____ If smoke disappears:

- Continue the flight with the faulty BLEED AIR system isolated.

_____ If smoke persists:

- CREW temperature controller MANUAL / 40 % HOT

_____ If smoke disappears:

- Continue flight and use CREW temperature controller as required to establish the appropriate cabin temperature. Do not select a position lower than 40 % HOT.

_____ If smoke persists:

- Bleed air CREW switch OFF
- APPLY SMOKE REMOVAL PROCEDURE starting at PHASE **2** (see 2-05-7).

Section 2
 Sub-section 05
 Page 4

DTM20103
 APPROVED
 REVISION 31

Appendix B



MYSTERE-FALCON 900

AIRPLANE FLIGHT MANUAL

EMERGENCY PROCEDURES



ELECTRICAL SMOKE OR FIRE

WARNING – Smoke and unusual odors

– or **AFT LAV SMOKE** light on (modification M2325 complied with).

PHASE 1

- Crew oxygen masks Donned – 100 % + EMERGENCY
- Smoke goggles Donned – Vent valve open
- Microphone selector MASK – Tested
-  light pushbutton On

ONLY IF NO FLAME IN CABIN:

- PASSENGER OXYGEN controller OVERRIDE
- Passenger masks Donned – Checked

PHASE 2

- Crew air gaspers Open

If the origin of the fire or smoke is evident:

- Suspected equipment Isolated

If the origin of the fire or smoke is not evident and **flight conditions****permit a total electrical power shutdown:**

- BAT 1, GEN 1, BAT 2, GEN 2, GEN 3 Off
- E. BATT switch (modification M2331 complied with) Depress / Off

- After smoke has stopped, determine which power system causes smoke to reoccur (bus A LH side with battery 1 or bus B RH side with battery 2) by switching the batteries on one at a time, one after the other:

- Suspected side, BAT switch Off
- Other side, BAT + GEN switch(es) On
- Do not tie buses.

If flight conditions do not permit a total electrical power shutdown, shutdown selectively:

- BAT 2 and GEN 2 switches Off
- A – B buses: FLIGHT NORM Checked
 - **BUS TIED** light Out
- PASSENGER temperature controller MANUAL / COLD

If smoke persists:

- AUTO / MAN pressure selector switch MAN
- BAT 2 and GEN 2 switches On
- BAT 1, GEN 1 and GEN 3 switches Off
- CREW temperature controller MANUAL / COLD

If fire is visibly verified to be out:

- Continue the flight.

If fire is not visibly verified to be out:

- **Land as soon as possible.**

DTM20103
APPROVED
REVISION 31

Cont'd next page

Section	2
Sub-section	05
Page	5

DASSAULT AVIATION Proprietary Data



ELECTRICAL SMOKE OR FIRE (cont'd)

PHASE 2 (cont'd)

If smoke persists:

- Crew air gaspers Open
- Descent to below 14,000 ft or to the safe altitude.

CAUTION

 * The following procedure must not be applied if flames are present in cabin or cockpit. *
 *

At 14,000 ft or below:

- UP-DN control UP

At a speed below 215 KIAS:

- LH direct vision window Open

PHASE 3

- Descent to 10,000 ft or to the safe altitude.

If smoke persists or fire is not visibly verified to be out:

- **Land as soon as possible.**

DASSAULT AVIATION Proprietary Data

Section 2
 Sub-section 05
 Page 6

DTM20103
 DGAC APPROVED
 REVISION 24

Appendix C



MYSTERE-FALCON 900
AIRPLANE FLIGHT MANUAL

EMERGENCY PROCEDURES

SMOKE AND UNUSUAL ODORS REMOVAL



PHASE 1

- Crew oxygen masks Donned - 100 % + EMERGENCY
- Smoke goggles Donned - Vent valve open
- Microphone selector MASK - Tested
-  light pushbutton On

ONLY IF NO FLAME IN CABIN:

- PASSENGER OXYGEN controller OVERRIDE
- Passenger masks Donned - Checked

PHASE 2

- Crew air gaspers Open
- CREW and PASSENGER temperature controllers MANUAL / COLD
- Descent to below 14,000 ft or to the safe altitude.

***** **CAUTION** *****
 * The following procedure must not be applied if flames are present *
 * in cabin or cockpit. *
 * *

At 14,000 ft or below:

- Pressurization switch DUMP

At a speed below 215 KIAS:

- LH direct vision window Open

PHASE 3


- Descent to 10,000 ft or to the safe altitude.
- _____ If smoke persists or fire is not visibly verified to be out:
 - Land as soon as possible.

DTM20103
EASA APPROVED
REVISION 26

Section 2
Sub-section 05
Page 7

DASSAULT AVIATION Proprietary Data

Appendix D

 <p>SOUTH AFRICAN CIVIL AVIATION AUTHORITY</p>	<p align="center">REPUBLIC OF SOUTH AFRICA</p> <p align="center">CIVIL AVIATION AUTHORITY</p> <p align="center">AERONAUTICAL INFORMATION CIRCULAR</p>	<p>CAA Private Bag x73 Halfway House 1685</p>
<p>Tel: (011) 545-1000 Fax: (011) 545-1465 E-Mail: ma@caa.co.za</p>		<p align="center">AIC Series D 023/2017 20 JUL 2017</p>

AIR NAVIGATION SERVICES

COMMUNICATION

ADS-B 1090 MHz and Mode S "Extended Squitter" AIRCRAFT TRANSPONDER REQUIREMENTS IN SOUTH AFRICA**1. Purpose**

The purpose of this AIC is to inform the South African ATM community of intended developments in terms of enhancing and improving Air Traffic Surveillance Services. It also serves as a means to open dialogue for the purposes of consultation with the Aviation Industry prior to the proposed implementation of the Surveillance Services.

In the Republic of South Africa, transponder equipage; and operation in CLASS A, and CLASS C airspace is mandated according to SA-AIP ENR 1.6.1 to ENR 1.6.5. Furthermore, Regulation 91.05.1 of the Civil Aviation Regulations, 2011 (CAR 2011) read together with the SA-CATS 91.05.1; provide further clarity and support to this ENR mandate.

2. Introduction

In order to continue with the provision of safe, orderly, expeditious and efficient Air Traffic Management solutions and associated services; it is necessary to continuously review the enabling technologies that allow for improved continuation of these services.

To this extent, the need to inform Aviation Industry of more flexible, efficient, and cost-beneficial Surveillance Technologies such as Automatic Dependant Surveillance-Broadcast (ADS-B) has been identified; with a view to replace legacy, less efficient, and more expensive Primary Surveillance Radar (PSR) and Monopulse Secondary Surveillance RADAR (MSSR) technologies.

Due to the increase traffic volumes, especially in complex terminal areas, the introduction of Mode Select (Mode S) transponders are also required to ensure operational performance of the surveillance sensors.

The positive gains in Total Surveillance System Performance that ADS-B and Mode S provides has been proved by other ANSP's; and as such, ADS-B been identified to be suitable for fitment on all relevant Instrument Flight Rules (IFR) and Visual Flight Rules (VFR) flights in the RSA in order to ensure that pertinent and essential information is fed to the Automated Air Traffic Management System, which is in support of the future operating environment.

3. General

If a new transponder is installed in an IFR or VFR aircraft, it is highly recommended that it be equipped with serviceable ADS-B and Mode S transponder in order to comply with the future effective dates for planned Mode S and ADS-B equipage.

Mode S and ADS-B Planned Dates of Applicability

The proposed fitment of approved ADS-B equipage is as follows:

2018 – IFR Forward fit: Any aircraft that is first registered on or after 1 January 2018 and is operated under IFR must carry a serviceable Mode S and ADS-B transponder that complies with the requirements below.

- 2 -

2020 – All IFR aircraft: On and after 1 April 2020 operated under IFR must carry a serviceable Mode S and ADS-B transponder that complies with the requirements below.

2020 –New aircraft and Newly installed transponders: Any aircraft that is first registered or modified by having its transponder replaced on or after 1 April 2020, and is operated in Class A, B, C or E airspace must carry a serviceable ADS-B and Mode-S transponder that complies with the requirements below.

Mode S and ADS-B Transponder Requirements

In order to realise the full operational benefits of ADS-B, it is recommended that the equipment meets the current standard 1090ES ADS-B Link Version 2 (RTCA/DO-260B/EUROCAE ED-102A) for transponders fitted to aircraft operating in South African airspace.

Aircraft that are additionally equipped with antennae fitted on to the top and bottom of the fuselage will have the benefit of line-of-sight to the evolving based services as well as terrestrial services (e.g. ACAS, ADS-B, etc).

(RTCA/DO-260B/EUROCAE ED-102A) transponders feature both ADS-B "out", as well as ADS-B "in" for the purposes of Traffic Information, Service Broadcast (TIS-B), and Flight Information.

In South Africa, (RTCA/DO-260B/EUROCAE ED-102A) compliant transponders shall include only those operating on 1090 MHz. This standard will expressly exclude the use of Universal Access Transceivers (UAT) that operates on 978 MHz.

In addition to meeting the above requirements, the equipment shall also be certified in accordance with the FAA or EASA (E)TSO-C166() or a later approved version.

The mode S transponder equipment shall be certified in accordance with the FAA or EASA (E)TSO-C112 or a later approved version.

The aircrafts unique 24 bit address' (otherwise known as the mode S code issued by the Authority) shall be strapped to the transponders without error and ensuring that it corresponds exactly with the binary or hexadecimal address issued. Confirmation of the correct strapping must be conducted by using the correct ramp test equipment. Application for this code must be made to the Authority using form CA 91-12 which can be found on the SACAA website and must be accompanied by the prescribed fee.

The GNSS position source shall be certified in accordance with FAA or EASA (E)TSO-C145a, (E)TSO-C146a or (E)TSO-C196a or later approved versions. Some later versions of GNSS receivers certified to (E) TSO-C129 may also meet the requirements, such as those having FDE and HPL features incorporated.

The altitude source equipment supplying the pressure altitude to be transmitted by the ADS-B equipment shall be certified in accordance with the FAA or EASA (E)TSO-C88a or a later approved version.

4. Conclusion

Installations carried out on South African registered aircraft to meet the above requirements must be carried out strictly in accordance with Part 21 and Part 43 of the CAR, 2011 and must be conducted by an Aircraft Maintenance Organisation holding the current and appropriate rating to do so.

For further information, please contact the ATNS ADS-B helpdesk at atads-b@atns.co.za


 DIRECTOR OF CIVIL AVIATION

Appendix E

Item	Wire number	Wd :	Identifier
1	1LC1B	64000204A7	COCKPIT LIGHTING
2	1HQ11A	640000501A2	LH BLOWER
3	3EM1A	620000301A1	OIL 3
4	L1FX	680000711C4	ADC1
5	L1RP	680000301A5	ADF1
6	L11SH	650000201B4	TCAS
7	L1CA	680000731A5	AFCS1 CMPTR
8	JA1A	620000101A4	IGNITION1
9	L31FV	680000851A7	EFIS
10	FL51A	640000601A5	AI PROBES
11	PW31A	610000106A1	SIGN WARN PWR
12	1WW1B	640000802A1	WARNING & INDICATION
13	1JW2A	620000101A4	IGNITION 1 TEST
14	L1RJ	680000771B4	FMS 1
15	L1RS	680000101A4	VOR 1
16	2WB41A	620000501A2	FUEL 2 SHUT OFF
17	L11FV	680000851A7	EADI LH
18	1HA14A	640000602A5	ANTI ICE
19	L21FV	680000851A7	EHSI LH
20	L1RV	680000101A4	DME 1
21	51FV	680000891B3	SYMBOL GEN 3
22	1FL11A	640000601A5	STATIC HEAT LH
23	1HN21E	640000302A6	AIRCONDITIONING
24	3HN2B	640000302A6	AIRCONDITIONING
25	1PP8AN	610000201A3	PANEL SHIELD
26	11SH	34-52-01-B4	ATC1
27	3HA30A	640000602A5	ANTI ICE ENGINE
28	QN11A	620000401A4	BP FUEL PUMP
29	1KK1A	620000101A4	STARTING
30	EK11A	620000404A5	FUEL LEVEL
31	1UTL1A16		UTILITY PLUG
32	1FP11A	640000901A4	IRS 1 BAT
33	WW3B	640000802A1	WARNING & INDICATION
34	FP31A	640000901A4	IRS 3 batt
35	1LM1A	630000401A2	LIGHTS
36	2QA1A	620000401A4	FUEL PUMP
37	1EJ1A	620000405A4	FUEL GAUGES
38	J101-E	34-55-91-A7	GPS 1
39	WW4B	640000802A1	WARNING & INDICATION
40	DL1C	601681500B2	FLAP POS
41	L1FF	680000611A3	DDRM 1
42	1QN4A	620000401A4	FUEL PUMP
43	L11CA	680000731A5	AFCS 1
44	1EP1A	620000107A6	ENGINE CMPTR
45	1FX1A	640000111A3	ARTHUR
46	1LK1A	640000201A8	INST. LIGHTING

47	1WW21A	640000802A1	TEST LIGHT
48	1LC1A	640000204A7	LIGHTING
49	1SQ	34-44-51-B1	WEATHER RADAR R/T
50	1LJ31A	630000402B1	EXTERNAL LIGHTS
51	1PA1A	610000101B4	DC POWER
52	1HA2B	640000602A5	AI ENGINE
53	WK3A	660000151A4	DIM/BRT BELTS SIGNS
54	LC17A	640000204A7	LIGHTING
55	2WW21A	640000802A1	TEST LIGHT
56	1WB1A	620000501A2	FIRE DET. EXT.
57	L11RJ	680000771	CDU 1
58	1KK4A	620000101A4	STARTING
59	QN14A	620000401A4	BP FUEL PUMP
60	1PD1B	610000101B4	DC POWER
61	1PE1B	610000101B4	DC POWER
62	WJ3A	660000151A4	DIM/BRIGHT
63	3HN4B	640000302A6	AIR COND.
64	1HA30A	640000602A5	AI ENGINE
65	3HA12A	640000602A5	AI ENGINE
66	1EP2B	620000107A6	ENGINE CMPTR
67	FG2A	640000901A4	IRS 1 BATT
68	1LM12B	630000401A2	LANDING LIGHT
69	1FL2A	640000601A5	PROBE HEATING
70	1KK2A	620000101A4	STARTING
71	EK1B	620000404A5	FUEL LEVEL
72	1LK4A	640000201A8	INST. LIGHTING
73	1FL32A	640000601A5	PROBE HEATING
74	FL22A	640000601A5	PROBE HEATING
75	HJ14A	640000604A7	AI WINGS
78	HH15A	640000605A2	WINDSHIELD HEAT
79	3EP2B	620000107A6	ENGINE CMPTR
80	3EP1D	620000107A6	ENGINE CMPTR
81	3PD2B	610000101B4	DC POWER
82	WJ1A	660000151xx	NO SMOKE
83	3EP1A	620000107A6	ENGINE CMPTR
84	LE121A	660000151A4	CABIN LIGHTS
85	1FL31A	640000601A5	PROBE HEATING
86	LJ21A	630000402B1	NAV/STROBE LIGHTS
87	3HU1A	640000604A7	AI WINGS
88	FL21A	640000601A5	PROBE HEATING
89	1HH1A	640000605A2	WINDSHIELD HEAT
90	1HU1A	30-16-04-A7	HP Bleed
91	1QA6A	28-24-01-A4	X-BP 1-2
92	1QA1A	28-24-04-A4	X-BP 1-2
93	EK13A	28-24-04-A5	FUEL LEVEL
94	LJ1A	33-44-02-B1	NAV/STROBE LIGHTS
95	HJ16A	30-16-04-A7	AI WINGS
96	1MK2A	30-47-01-A3	WINDSHIELD WIPERS

97	3KK1A	80-01-01-A4	AUTO IGNITION
98	3KK1B	80-01-01-A4	AUTO IGNITION
99	3KK1D	80-01-01-A4	AUTO IGNITION
100	1FL1A	30-36-01-A5	PROBE HEATING
101	HH31A	30-46-05-A3	WINDSHIELD HEAT
102	3452-0500-20	ADSB-STC	AIU INTERFACE
103	1LK1B	33-12-01-B2	INST. LIGHTING
104	3JW2A	80-01-01-A4	AUTO IGNITION
105	1MK1C	30-47-01-A3	WINDSHIELD WIPERS
106	1LFV	34-28-51-A7	SG1
107	1LFP	34-45-61-A2	IRS 1
108	12GP		EGPWS
109	1SA	34-45-01-A2	RAD ALT
110	61FV	34-28-91-B3	MFD/ WRD
111	1LRC	23-11-01-B1	VHF 1
112	L11RE	23-14-01-A9	HF CONTROL
113	21LCA	22-17-31-A5	YAW DAMPER
114	L1RL	23-43-01-D2	ICS LH
115	L51LK	33-12-01-A8	ANNUNC LH
116	L41CA	22-17-31-A5	AFCS 1 ADVIS
117	L21fp	34-45-18-A6	IRS 3
118	L1RE	23-14-01-A9	HF 1 PWR
119	1WL1A	31-58-30-A2	AUDIO WARN A
120	1QN14A	28-24-01	ST-BY PUMP
121	HJ15A	30-	AI WINGS

Appendix F

With reference to SACATS, 2011 139.02.15 (AIRPORT RESCUE AND FIREFIGHTING), the following extracts of the SACAR's define ARFF categorisation.

Airport Category Classification matrix

Column I	Column II	Column III	Column IV
Aerodrome Category	Aircraft Overall Length	Aircraft Maximum Fuselage Width	Number of firefighting Vehicles
1.	N/A	N/A	N/A
2.	N/A	N/A	N/A
3.	at least 12 m but less than 18 m	3 m	1
4.	at least 18 m but less than 24 m	4 m	1
5.	at least 24 m but less than 28 m	4 m	1
6.	at least 28 m but less than 39 m	5 m	2
7.	at least 39 m but less than 49 m	5 m	2
8.	at least 49 m but less than 61 m	7 m	3
9.	at least 61 m but less than 76 m	7 m	3
10.	at least 76 m but less than 90 m		3

(a) The level of protection provided at an Airport for rescue and firefighting shall be based on the longest aeroplanes and its fuselage width using the Airport.

(b) The level of protection shall be appropriate to the Airport category determined where the number of movements of the aeroplanes in the highest category using the Airport is more than 700 total in the busiest consecutive three months.

(c) During reduced activity, of less than 700 total movements for the busiest consecutive three months for aeroplanes in the highest category, for Airports above category 4 the level of protection available shall be no less than that needed for the highest category of aeroplane planned to use the Airport, during the time of the actual movements and may be reduced by one level during other times.

(d) When using the classification matrix contained in paragraph 1 above, Airports qualifying for the issue of an Airport licence in category 4, may provide an aircraft Category 3 firefighting service at all times if –

(i) a full risk assessment has been carried out by the operator which indicates that even with a lower category firefighting service, an acceptable level of safety can be maintained.

(ii) the level of Airport rescue and firefighting services protection provided is no less than that required for a category 3 level of protection and includes both the foam, dry chemical powder and rescue equipment requirements.

(iii) fully trained and permanently appointed firefighting personnel are provided.

(iv) for category 3 aircraft firefighting service, each firefighting vehicle is capable of discharging its content at the required application rate as indicated in Column VI of the minimum useable amount of extinguishing agent table in the appropriate mixture. Where nitrogen is used as the propellant to eliminate possible faulty pump operational systems; the full (pre mixed) content can be discharged as firefighting foam. This does not preclude the use of a firefighting vehicle fitted with a pump and foam induction system provided that the full content can be discharged at the required application rate.

(e) For Airports issued with a category 3 license the level of firefighting service and equipment required shall be based on a risk assessment and shall not exceed the requirement contained in the classification matrix. The risk assessment shall consider number of movements, prevalent aeroplane size, operational hours, minimum level of pilot proficiency, aircraft types, location, etc. Notwithstanding the aforementioned, for category 3 Airports with more than 700 total movements during the busiest consecutive three months, the level of service shall comply with the classification matrix at all times.

Minimum Useable Amounts of Extinguishing Agent

Aerodrome Category	Foam meeting performance level A		Foam meeting performance level B		Foam meeting performance level C		Complementary agents	
	Water (L)	Discharge rate foam solution/minute (L)	Water (L)	Discharge rate foam solution/minute (L)	Water (L)	Discharge rate foam solution/minute (L)	Dry chemical powders (kg)	Discharge rate (kg/sec)
1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	1 800	1 300	1 200	900	820	630	135	2.25
4	3 600	2 600	2 400	1 800	1 700	1 100	135	2.25
5	8 100	4 500	5 400	3 000	3 900	2 200	180	2.25
6	11 800	6 000	7 900	4 000	5 800	2 900	225	2.25
7	18 200	7 900	12 100	5 300	8 800	3 800	225	2.25
8	27 300	10 800	18 200	7 200	12 800	5 100	450	4.5
9	36 400	13 500	24 300	9 000	17 100	6 300	450	4.5
10	48 200	16 600	32 300	11 200	22 900	7 900	450	4.5

(v) These firefighting vehicles shall have both a hand-line and a roof mounted turret/mirror. A discharge distance of at least the length of the longest aeroplane using the Airport is required through the vehicle turret.

(vi) The fire appliances deployed shall be a self-propelled 4 X 4 vehicle that can achieve the required response times of 0 to 80 km/h within 25 seconds as depicted for Rapid Intervention Vehicles when fully laden and have a maximum speed of not less than 105 km/h.

(vii) The ancillary equipment to be carried on the vehicle shall consist of the equipment depicted in the rescue equipment list below.

(e) The Airport operator shall ensure that both principal and complementary agents are provided at an Airport and the principal extinguishing agent shall be –

- (i) a foam meeting the minimum performance level A; or
- (ii) a foam meeting the minimum performance level B; or
- (iii) a foam meeting the minimum performance level C; or
- (iv) a combination of these agents; except that the principal extinguishing agent for Airports in categories 1 to 3 shall preferably meet a performance level B or C foam.

(f) At Airports where operations by aeroplanes larger than Airport category are planned, the quantities of water shall be recalculated and the amount of water for foam production and the discharge rates for foam solution shall be increased accordingly.

- (g) The quantity of foam concentrates that is separately provided on vehicles for foam production shall be in proportion to the quantity of water provided and the foam concentrate selected.
- (h) The amount of foam concentrate provided on a vehicle shall be sufficient to produce at least two loads of foam solution.
- (i) Supplementary water supplies, for the expeditious replenishment of rescue and firefighting vehicles at the scene of an aircraft accident, shall be provided.
- (j) Dry chemical powders shall only be substituted with an agent that has equivalent or better firefighting capabilities for all types of fires where complementary agent is expected to be used.
- (k) A reserve supply of foam concentrate equivalent to 200% of quantities and 100% of complementary agent including propellant gas shall be maintained at the Airport for vehicle replenishment purposes. If a major delay in replenishment is anticipated the amount of reserve supply shall be increased as determined by the risk assessment.
- (l) Where a major delay in the replenishment of the supplies is anticipated, the Airport operator shall ensure that a contingency plan is put in place to address the delay.

Appendix G

ZENITH AIR	ZS-DFJ		AIRCRAFT: SERIAL NO:	F900B 141
MINIMUM EQUIPMENT LIST	EASA MMEL REV. NO: 10 DATE: 22/07/2011		MEL REV. NO: Initial DATE: 21/05/2018	
1. SYSTEM, SEQUENCE NUMBERS & ITEM	2. REPAIR CATEGORY		3. NUMBER INSTALLED	4. NUMBER REQUIRED FOR DISPATCH
			5. REMARKS AND EXCEPTIONS	
34 NAVIGATION				Refer to (O) & (M) Section for procedures
4. Reversion Controller Panel (RCP) (1) F900B	C	2	1	One may be inoperative provided Display Controller Panels (DC 820) are operative.
5. Remote Instrument Controller (RI 820) (ASEL / DH Selection)	C	1	0	(O) May be inoperative provided: - As required by Regulations, Ref. (See Appendix Q) - RVSM operations are not planned. [OPER 22-1 on section 2-22]
7. Attitude and Heading System (AHS) (1) Inertial Reference System (IRS)	D	3	2	Note: For specific RNAV operations, refer to [OPER 34-0 on section 2-34]. One may be inoperative.
	A	3	1	(O) One or more may be inoperative provided: - Standby horizon and standby magnetic compass are operative, - Monitoring of the remaining operating IRS by the standby horizon and standby magnetic compass is performed with care, - Flight is performed in daylight VMC conditions, - Repairs are made within three consecutive calendar days. [OPER 34-7.1 on section 2-34]
(2) Standby Horizon and Power Supply (a) F900B	B	1	0	May be inoperative for daylight VMC operation only.
(Continued)				

ZENITH AIR		ZS-DFJ	
MINIMUM EQUIPMENT LIST: DEFINITIONS, ABBREVIATIONS & NOTES			
AIRCRAFT:	F900B	EASA MMEL REV.:	10
SER. NO:	141	DATE:	22/07/2011
		MEL REV.:	Initial Issue
		DATE:	21/05/2018

DEFINITIONS, ABBREVIATIONS & EXPLANATORY NOTES

DEFINITIONS

1. The System numbers are based on the Air Transport Association (ATA), Specification Number 100 and items are numbered sequentially.
2. The MMEL-related Dispatch Assistance information consists of:
 - The Fault Guide Dispatch Assistance (FGDA), reference DGT 118448,
 - This approved MMEL, and
 - The associated Operational and Maintenance procedures, gathered in the "Maintenance and Operating procedures" document, reference DTM611.
3. The MMEL Item List provides the list of component, instrument, equipment, system, or function which may be inoperative prior to dispatch. Items are gathered by ATA chapter and provided under a table format. The structure of the MMEL item list table is as follows:
 - 3.1. **System & Sequence Numbers Item** - Column (1) - details the component, instrument, equipment, system, or function listed.
 - 3.2. **Rectification Interval** - Column (2) - Inoperative items, deferred in accordance with the MEL, must be rectified at or prior to the rectification intervals established by the following letter designators:
 - 3.2.1 **Category A:**
No standard interval is specified. However, items in this category shall be rectified in accordance with the conditions stated in the "Remarks or Exceptions" column - Column (5)
 - (i) Where a time period is specified in calendar days or flight days, the interval excludes the day of discovery.
 - (ii) Where a time period is specified other than in calendar days or flight days, it shall start at the point when the defect is deferred in accordance with the operator's approved MEL.
 - 3.2.2 **Category B:**
Items in this category shall be rectified within three (3) calendar days, excluding the day of discovery.
 - 3.2.3 **Category C:**
Items in this category shall be rectified within ten (10) calendar days, excluding the day of discovery.

Appendix H

FALCON 900B AIRCRAFT MAINTENANCE MANUAL




Figure 1: EFIS system description

Right hand reversion controller panel was inoperative

Appendix I



United States of America
Department of Transportation
Federal Aviation Administration

Supplemental Type Certificate

Number: ST02972NY

This certificate issued to: Dassault Aircraft Services (DAS)
191 North DuPont Highway, New Castle, DE 19720

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified herein meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product - Type Certificate Number: A46EU Make: Dassault Aviation
Model: Mystere-Falcon 900

Description of Type Design Change:

Installation of ADS-B Out system in accordance with Dassault Aircraft Services (1) Master Data List, F9BW-D0025-005, Revision IR, dated 07/14/2014, or later FAA approved revision. (2) Instructions for Continued Airworthiness (ICA) F9BW-D0025-155, Revision B, dated 03/07/2014 or later FAA accepted revision. The ICA and its contents must be incorporated into the operator's maintenance program. (3) Airplane Flight Manual Supplement (AFMS) F9BW-D0025-150, Revision I/R, dated 07/14/2014 for Config. 1 (DO-260A), or F9BW-D0045-150, Revision IR, dated 08/31/2016 for Config. 2 (DO-260B), or later FAA approved revisions.

Limitations and Conditions:

- (1) STC ST02970NY for installation of Honeywell GPS Landing System Sensor Unit (GLSSU) is a pre-requisite for this alteration, and must be installed either prior to, or in conjunction with this alteration.
- (2) The installer must determine whether this design change is compatible with previously approved modifications.

(See Continuation on Page 3 of 3)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, and revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: 8/6/2013

Date reissued: 11/25/2014

Date of issuance: 7/14/2014

Date amended: 09/1/2016

By direction of the Administrator

Signature

Title Administrator, ODA-955740-NE

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both. This certificate may be transferred or made available to third persons by licensing agreements in accordance with 14 CFR 21.47. Possession of this Supplemental Type Certificate (STC) document by persons other than the STC holder does not constitute rights to the design data nor to alter an aircraft, aircraft engine, or propeller. The STC's supporting documentation (drawings, instructions, specifications, flight manual supplements, etc.) is the property of the STC holder. An STC holder who allows a person to use the STC to alter an aircraft, aircraft engine, or propeller must provide that person with written permission acceptable to the FAA. (Ref. 14 CFR 21.120).

FAA Form 8110-2 (8/13)

Page 1



United States of America
Department of Transportation
Federal Aviation Administration

Supplemental Type Certificate

(Continuation Sheet)

Number: ST02972NY

Date Amended: September 1, 2016

Limitations and Conditions (continued)

- (3) If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

Certification Basis

Based on 14 CFR §§ 21.115 and 21.101, and the FAA policy for significant changes in FAA Order 8110.48, the certification basis for the Dassault Aviation, model Mystere-Falcon 900 is as follows:

(1) The type certification basis for Dassault Aviation, Model Mystere-Falcon 900 airplane is shown on TCDS A46EU for parts **not changed or not affected** by the change.

(2) The certification basis for parts **changed or affected** by the change since the reference date of application August 6, 2013, is based upon part 25 as amended by Amendment 25-56 with the exception of those listed above amendment 25-56, below.

Regulations at later amendment than 25-56

14 CFR Part	Amendment
25.625(a)	25-72
25.869(a)(4)	25-72
25.1581(a)(2)(b)(d)	25-72

.....END.....

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both. This certificate may be transferred or made available to third persons by licensing agreements in accordance with 14 CFR 21.47. Possession of this Supplemental Type Certificate (STC) document by persons other than the STC holder does not constitute rights to the design data nor to alter an aircraft, aircraft engine, or propeller. The STC's supporting documentation (drawings, instructions, specifications, flight manual supplements, etc.) is the property of the STC holder. An STC holder who allows a person to use the STC to alter an aircraft, aircraft engine, or propeller must provide that person with written permission acceptable to the FAA. (Ref. 14 CFR 21.125).

FAA Form 8110-2 (8/13)

Page 3

Appendix J

B. PROCEDURE

(1) Transponders TDR-94D (P/N 622-9210-501) #1 and #2 shall be installed in the Existing Avionics Rack in the L/H Crew Closet and in the Nose Radio Rack R/H Side respectively, according to the document entitled "#1 & #2 DO260B TRANSPONDER INSTL".

(2) Annunciator Interface Units (AIU's) (P/N BA-440) shall be installed in the respective locations under the cockpit floor between frames 2 and 3 and also between stringers 18 and 19 according to the document entitled "BA-440 FILTER / ROUTER INSTALLATION".

May 16, 2018
Original Issue

F900-S007
Page 7 / 13

**SERVICE BULLETIN****FALCON 900****F900-S007**

(3) AIU Annunciator (P/N LED-50-17-BB-E1GYC) and ADS-B System and Transponder Annunciators (P/N LED-50-17-BB-E1GYB) shall be installed in the respective locations in the cockpit according to the documents entitled "ANNUCIATOR INSTL (ADS-B OUT)".

(4) Wiring shall be installed according to the documents entitled:

- ATC: ADS-B DO-260B

(5) Transponders TDR-94D shall be connected to GPS, according to the document entitled "ATC: ADS-B OUT - D0260B".

(6) Transponders TDR-94D shall be connected to AIU and respective annunciators, according to the documents entitled:

- "ATC: ADS-B OUT DO-260B"

GENERAL NOTES:

1. LRU LOCATIONS ARE SHOWN FOR REFERENCED ONLY.
2. INSTALLATION TO BE ACCOMPLISHED IN ACCORDANCE WITH THE FOLLOWING:
 - > AIRCRAFT STANDARD PRACTICES DEFINED WITHIN FAA AD-430, AMM, AND OEM PRACTICES AS APPLICABLE.
 - > SAS 16-1025 FOR WIRE ROUTING AND BUNDLE SEPARATION.
 - > SAS 16-1024 FOR REDUCING THE EFFECTS OF VIBR.
 - > SAS 16-1027 FOR WINDLING OF COPPER WIRE.
3. THIS DRAWING REFERS TO THE WIRE HARNESS CLAMPING AND SEPARATION REQUIREMENTS ASSOCIATED ONLY WITH THE NEW WIRING INSTALLATION.
4. CONSISTENT WITH THE ACCEPTABLE MEANS OF ADVISORY CIRCULAR 20-10, 20-16, AND 43-13-8, THE PHILOSOPHY FOR WIRE ROUTING DESIGN IS AS FOLLOWS:
 - > TO ADDRESS THE PHYSICAL DIRECT EFFECTS OF A WIRING FAULT (E.G. ARCING, HEAT, INSULATION FLASHOVER, ETC.) ALL NEW WIRE BUNDLES ARE TO BE PROUDLY CLAMPED/SUPPORTED AND TIED AT INTERVALS SUCH THAT AN ASSUMED BROKEN CLAMP PLUS A BROKEN WIRE WOULD NOT ALLOW THE BROKEN WIRE TO CONTACT THE OTHER WIRE BUNDLES.
 - > NEW WIRE BUNDLES ARE TO BE ROUTED SEPARATELY FROM EXISTING BUNDLES.
 - > IN THE EVENT OF SPACE LIMITATIONS, IT IS PERMISSIBLE TO ROUTE NEW WIRING WITH OTHER CONCURRENTLY INSTALLED WIRING WITHOUT PHYSICAL SEPARATION, THE SIGNALS IN THE WIRING FOR EACH OF THESE SYSTEMS MUST BE EVALUATED AND DETERMINED TO BE LOW LEVEL POWER, OF LITTLE ELECTROMAGNETIC INTERFERENCE RISK, AND CONSISTENT WITH THE WIRE TYPES CONTAINED IN THE WIRING. RELEVANT WIRE BUNDLES ARE TO BE CLAMPED AND SECURED CONSISTENT WITH THE STANDARDS SET FORTH HEREIN.
 - > MINIMUM BEND RADIUS FOR COAXIAL CABLES MUST NOT BE LESS THAN SIX TIMES THE CABLES DIAMETER.
 - > MINIMUM BEND RADIUS FOR ALL NEW WIRE BUNDLES MUST NOT BE LESS THAN TEN TIMES THE OUTSIDE DIAMETER OF THE LONGEST WIRE IN THAT BUNDLE. A BEND RADIUS OF SIX TIMES MAY BE USED AT BUNDLE BREAKOUTS.
 - > ALL SERVICE LOOPS SHALL MAINTAIN AT LEAST A MINIMUM BEND RADIUS OF THREE TIMES THE ENTIRE DIAMETER OF THE WIRE HARNESS.
 - > IN ADDITION TO THE SEPARATION AND ROUTING REQUIREMENTS CONTAINED HEREIN, CAREFUL CONSIDERATION MUST ALSO BE MADE TO THE WIRE ROUTING REQUIREMENTS CONTAINED IN THE BASSAULT FALCON 900 WIRING MANUALS.
5. WHEN ROUTING NEW WIRING, MAINTAIN 8" SEPARATION FROM FUEL QUANTITY WIRING.
6. ROUTE ELECTRICAL WIRES AND CABLES ABOVE FUSED LINES AND PROVIDE A 6" SEPARATION FROM ANY FLAMMABLE LIQUID, FUEL, OR OXYGEN LINE. FUEL TANK WALL, OR OTHER LOW VOLTAGE WIRING THAT ENVIERS A FUEL TANK AND REQUIRES ELECTRICAL ISOLATION TO PREVENT AN IGNITION HAZARD.
7. WHERE 8" SPACERS CANNOT PRACTICALLY BE PROVIDED, A MINIMUM OF 2" MUST BE MAINTAINED BETWEEN WIRING AND SUCH LINES RELATED EQUIPMENT. FUEL TANK WALLS AND LOW VOLTAGE WIRING THAT ENVIERS A FUEL TANK. SUCH WIRING SHOULD BE CLOSELY CLAMPED AND PROUDLY SUPPORTED AND TIED AT INTERVALS SUCH THAT CONTACT BETWEEN SUCH LINES RELATED EQUIPMENT, FUEL TANK WALLS OR OTHER WIRES, WOULD NOT OCCUR, ASSUMING A BROKEN WIRE AND/OR A MISSING WIRE TIE AND CLAMPS.
8. ALL NEW BUNDLES FOR #1 SYSTEMS WILL BE ROUTED DOWN THE LEFT SIDE OF THE AIRPLANE AND ALL NEW BUNDLES FOR #2 SYSTEMS WILL BE ROUTED DOWN THE RIGHT SIDE OF THE AIRPLANE. DEVIATIONS OF THIS WILL BE NOTED ON AN INDIVIDUAL BASIS.
9. TECHNICIAN IS TO ENSURE THAT THE PROPER SIZE CLAMP IS USED FOR THE BUNDLE.
10. WIRE IN THIS AREA IS LESS THAN 1/2 INCH FROM EXISTING WIRING.
11. TECHNICIAN IS TO USE STRING TIE AS REQUIRED.
12. IN CASES WHERE NEW WIRE BUNDLE DIAMETER DIFFERS FROM EXISTING WIRE BUNDLE, REPLACE EXISTING CLAMPS ACCORDING TO TABLE 1. RE-USE EXISTING SCREWS, WASHERS, AND CAPTIVE HARDWARE UNLESS OTHERWISE SPECIFIED.
13. IN CASES WHERE CLAMPS ARE NOT PRACTICAL OR POSSIBLE, THE USE OF ALTERNATE METHODS OF TIGHTENING BUNDLE SHOWN IN "DETAIL C" IS PERMITTED PROVIDED EVERY FOURTH STRONGER (OR SOONER) IS A WEA. CLOSURE CLAMP.
14. TECHNICIAN IS TO ENSURE THAT THE PROPER SIZE TIE STRAP IS USED FOR THE BUNDLE; SEE TABLE 2.
15. WHEN CLAMP SPACERS ARE REQUIRED, TECHNICIAN IS TO ENSURE THAT THE PROPER SIZE SPACER IS USED FOR THE BUNDLE; SEE TABLE 3.
16. TECHNICIAN IS TO ENSURE THAT THE APPROPRIATE STAND-OFF SPACER IS USED FOR THE SPECIFIC BUNDLE NEEDS; SEE TABLE 4.

DETAIL A
TYPICAL WIRE BUNDLE INSTL WITH 1/2" SEPARATION FROM EXISTING BUNDLE

DETAIL B
TYPICAL WIRE BUNDLE CLAMPING TECHNIQUES FOR SEPARATION FROM EXISTING BUNDLES

DETAIL C
ALTERNATIVE METHOD OF SECURING NEW WIRE BUNDLE TO EXISTING BUNDLE WHEN CLAMPS ARE NOT PRACTICAL OR POSSIBLE

DETAIL D
TYPICAL WIRE BUNDLE CLAMPING TECHNIQUES FOR SEPARATION FROM EXISTING BUNDLES

TABLE 1

WIRE BUNDLE DIA.	CLAMP P/N
1-5/16	MS21919BH21
1-3/4	MS21919BH20
1-3/8	MS21919BH19
1-1/8	MS21919BH18
1-1/4	MS21919BH17
1	MS21919BH16
15/16	MS21919BH15
1 1/2	MS21919BH14
1 1/8	MS21919BH13
5/4	MS21919BH12
5/8	MS21919BH10
9/16	MS21919BH9
7/16	MS21919BH7
3/8	MS21919BH6
5/16	MS21919BH4
1/4	MS21919BH4
3/16	MS21919BH3
1/8	MS21919BH2

RECOMMENDED CLAMP PART NUMBER FOR DESIGNATED WIRE BUNDLE DIAMETER

TABLE 2 **TABLE 3** **TABLE 4**

TIE STRAP P/N	SPACER P/N	SPACER P/N	SPACER P/N
MS3367-1-9	MS43303-10	FS08700010011/1"	
MS3367-2-9	MS43303-24	FS08700010011/1 1/4"	
MS3367-3-9	MS43303-56C		
MS3367-5-9	MS43303-65C		

TECHNICIAN TO DETERMINE THE APPROPRIATE SIZES REQUIRED WHEN SELECTING TIE STRAPS OR SPACERS AS NECESSARY FOR BUNDLES.

P/N	DESCRIPTION	QTY	REVISION
A/N 7874-21	ANGLE BRACKET	1	DISCART
A/N MS43303-X	SPACER	1	DISCART
A/N MS3367-1-9	TIE STRAP	1	DISCART
REF 304-5	STRING TIE	1	BROOKS PRODUCTS, INC.
A/N MS31919BH1	CLAMP	1	DISCART
A/N MS304213	WASHER	1	DISCART
A/N MS114870135P	WASHER	1	DISCART
A/N MS3367-1-9	TIE STRAP	1	DISCART
A/N FS0870001001	SPACER STAND-OFF	1	DISCART
REF 3877-429	SPACER STAND-OFF	1	DISCART
A/N FS0870001001	SPACER STAND-OFF	1	DISCART
REF 3877-429	SPACER STAND-OFF	1	DISCART
REF 3877-429	SPACER STAND-OFF	1	DISCART

Appendix K



Dassault Aircraft Services
191 North DuPont Highway
New Castle, DE 19720

Document Number:	Rev:	Date:
F9BW-D0045-210-1	IR	22-AUG 16

NOTES:

1. No additional load for the added Led annunciators as these items are supplied electrical power through the cockpit 5 AMP 14/28V dimming circuit and their load when illuminated is insignificant.
2. Electrical load values presented herein for each item reflect the manufacturer's specifications.

CONCLUSION:

The installing agency is responsible to attach this document to the existing electrical load reports for the aircraft upon completion of the installation and to verify the individual busses loads are not exceeded for all phases of flight.