

MANDATORY SERVICE

Pacific Aerospace Limited
Airport Road, Hamilton
Private Bag 3027, Hamilton 3240, New Zealand
TEL +6478436144 FAX +6478436134

EMAIL pacific@aerospace.co.nz WEB www.aerospace.co.nz PACSB / XL / 091 ISSUE 3

WING L/E TANK ABRASION REPAIR & PATCH

1. PLANNING INFORMATION

A. <u>EFFECTIVITY</u> All PAL 750XL aircraft up to and including S/N 135 (except S/N 113).

B. <u>REASON</u>

To repair or prevent chafing to wing leading edge due to rubbing by the

ventilation ducting.

C. <u>DESCRIPTION</u> Part A – Wing L/E tank repair where

chafing has occurred on the leading edge.

leading edge.

Part B – Wing L/E tank anti-abrasion

patch installation.

D. <u>COMPLIANCE</u> Inspect for chafing – at next 150 hour

check.

If chafing is found:

- Repair IAW Part A before further

flight.

If chafing is not found:

- Apply Part B after receipt of parts

and before 01 April 2018.

E. <u>APPROVAL</u> By delegated authority.

F. <u>TOOLING</u> N/A

G. <u>WEIGHT AND BALANCE</u> No change

H. REFERENCE PAL MOD PAC/XL/0319

I. HOURS REQUIRED Part A – 8 Hours

Part B – 1 Hour

J. WARRANTY COVER Normal Warranty conditions apply

Issued: 15 March 2018 Page 1 of 4

BULLETIN




2. INSPECTION INSTRUCTIONS

Inspect the leading edge skin of both wings at the wing root and check whether there are chafing marks. After inspection, proceed as follows:

- If chafing marks are found, apply Part A and Part B of this Service Bulletin;
- If there are no chafing marks, apply Part B of this Service Bulletin.

3. PART A - ACCOMPLISHMENT INSTRUCTIONS

Repair Wing L/E Tank Abrasion



Note: Item 11 is Doubler patch – Alc.Sheet, 0.025 thick 2024-T3
Item 15 is Adhesive sealant – AMS-S8802
Item 17 is Rivet AD 42 SB (POP)

Note 2: Repair this area IAW FAA AC43.13-1B Fig 4-16

<u>VIEW ON UNDERSIDE – R.H. WING</u> L.H. WING REPAIR SIMILAR (AS REQUIRED)

FIGURE 1 REPAIR WING L/E TANK ABRASION


Page 2 of 4 Issued: 15 March 2018



- 1) Blend out gouges in skin to remove sharp corners (ratio 20:1).
- 2) Where gouges are located outside the repair patch perimeter as drawn, extend the patch, replicating the indicated fastener pitching as required. Make sure blended area is within rivet attachment area, if the patch exceeds 6" x 6", contact PAL for further information
- 3) If patch rivets are required thru the wing inboard rib, ensure wing tank sealing is maintained/reinstated and replace rivets with the same P/N MS20470 AD4 solid rivets in existing locations (not the AD 42 SB rivet).
- 4) Remove any paint or primer between the mating surfaces and lightly scuff using scotchbrite. Clean with Prepsol/Acetone and allow to dry thoroughly. Apply AMS-S-8802 adhesive sealant liberally to mating surfaces ensuring no air gaps will result. Rivet the doubler patch in place while sealant is still wet.
- 5) Prime and paint in accordance with maintenance manual Chapter 20.
- 6) Install Teflon protection doublers as detailed in Part B of this Service Bulletin.

4. PART B - ACCOMPLISHMENT INSTRUCTIONS

Wing L/E Tank Anti-Abrasion Patch



Note: Item 11 is Anti-abrasion patch – Teflon Sht. 1mm THK. Etched Item 15 is Adhesive sealant – Sikaflex 221

VIEW ON UNDERSIDE – R.H. WING L.H. WING OPPOSITE HAND

FIGURE 2 WING L/E ANTI-ABRASION PATCH

- 1) Ensure mating surfaces of anti-abrasion patch and L/E skin are clean and free from dust or grease before bonding the anti-abrasion patch to the wing L/E skin.
- 2) Apply adhesive sealant on mating surfaces of anti-abrasion patch and wing L/E skin. Install the anti-abrasion patch as shown.

Issued: 15 March 2018 Page 3 of 4



5. **CERTIFICATION**

Record compliance with Part A and/or Part B of this bulletin in the aircraft Log Book.

6. MATERIAL REQUIRED:

Part A

<u>Description</u>	Part Number	Qty Required
Rivet	AD 42 SB (POP)	A/R
Adhesive Sealant – PRC type	AMS-S8802	A/R
Repair Patch – ALC. SHT025	11-03159-11	A/R
THK. 2024-T3		

Part B

<u>Description</u>	Part Number	Qty Required
Adhesive Sealant	Sikaflex 221	A/R
Anti-abrasion patch – Teflon SHT. 1mm THK. ETCHED	11-03161-11	2

Page 4 of 4 Issued: 15 March 2018