PACIFICAEROSPACE

Pacific Aerospace Limited Airport Road, Hamilton Private Beg 3027, Hamilton 3240, New Zealand

TEL +6478436144 FAX +6478436134 EMAIL pacific@aerospace.co.nz WEB www.aerospace.co.nz

Β.

PACSB / XL / 094 ISSUE 2

SERVICE

# PITOT-STATIC SYSTEM – PITOT-STATIC TUBES SUPPORT CLAMP

### 1. PLANNING INFORMATION

- A. <u>EFFECTIVITY</u> PAL 750XL aircraft up to and including S/N 220.
  - REASONProduction Inspection of installed Pitot-Static<br/>plumbing, identified a potential hazard.<br/>Insufficient clearance between pitot plumbing and<br/>primary support at flame arrestor intersection,<br/>could result in chafing of the pitot tube.
- C. <u>DESCRIPTION</u> Install an additional support clamp for Pitot-Static tube support (located next to port flame arrestor), protect plumbing with spiralwrap and fix pitot and static tubes separation to protect pitot-static plumbing from possible chafing.
- D. <u>COMPLIANCE</u> At next 300 hr check. After complying with this Service Bulletin, refer to Maintenance Manual Chapter 34 for the ongoing Airworthiness Inspections of the Pitot-Static system.
- E. <u>TOOLING</u> No special tools are required.
- F. <u>WEIGHT AND BALANCE</u> No change.
- G. <u>REFERENCE</u> 750XL Maintenance Manual.
- H. <u>HOURS REQUIRED</u> 1 hour.
- I. <u>WARRANTY COVER</u> Normal Warranty conditions apply.

# PACIFICAEROSPACE

#### 2. ACCOMPLISHMENT INSTRUCTIONS

(Refer to Figure 1)

- 1) Remove the cabin lining at STN 115.34 to access area of the flame arrestor.
- 2) Inspect the pitot static tubing for damage adjacent to the flame arrestor. If damage is found, repair or replace the tubing and carry out a pitot & static leak check.
- 3) Install pitot-static lines supporting clamps as shown in Figure 1. Use alternative way shown in Figure 2 if pitot-static lines traced between the flame arrestor and fuselage skin.
- 4) Ensure clamps supporting pitot-static lines are located as depicted to prevent low points from forming.
- 5) Protect Pitot-Static plumbing with spiral wrap. Use either existing or additional spiral wrap as required.
- 6) Fix pitot and static tubes separatly using cable tie and 8mm-length poli-flo tube as spacer.
- 7) Re-install the cabin lining at STN 115.34.




FIGURE 1 PITOT-STATIC SYSTEM – PITOT-STATIC LINES AND FLAME ARRESTOR INTERSECTION






FIGURE 2 PITOT-STATIC SYSTEM – PITOT-STATIC LINES AND FLAME ARRESTOR INTERSECTION (ALTERNATIVE)

# PACIFICAEROSPACE

## 3. CERTIFICATION

Record compliance with this Service Bulletin in the aircraft Log Book.

### 4. MATERIAL REQUIRED:

<b>Description</b>	Part Number	<b>Qty Required</b>
SUPPORT CLAMP	MS21919-WDG28	1
SUPPORT CLAMP	MS21919-WDG4	1
SCREW	AN525-832-R8	1
WASHER	AN960-8	1
NUT, SELF LOCKING	MS21044-N08	1
CABLE TIE	TY23M	1
SPIRAL WRAP	SW200FRP 1/4	200 mm
POLI-FLO TUBING	44PN	8 mm