PACIFICAEROSPACE

MANDATORY SERVICE

Pacific Aerospace Limited Airport Road, Hamilton Private Bag 3027, Hamilton 3240, New Zealand

TEL +6478436144 FAX +6478436134 EMAIL pacific@aerospace.co.nz WEB www.aerospace.co.nz

PACSB / XL / 115 ISSUE 3

BULLETI

INSPECTION / REPLACEMENT AILERON PIVOT FORK ASSEMBLY

1. PLANNING INFORMATION

A. <u>EFFECTIVITY</u> <u>MODEL</u> <u>S/N</u>

750XL (NZ) Up to S/N 216, and S/N 220

750XL (CN) 8001, 8002

B. REASON Addition of retaining features to the aileron

pivot fork bearing.

Issue 3 adds the washer P/N AN960-516 as

optional for the P/N AN960-516L.

C. DESCRIPTION Part A – Daily inspection.

Inspect the bearing assemblies at

both fork ends for security.

Part B – Install retaining washers, and a new

bolt secured with a castellated nut

and split pin.

D. COMPLIANCE Part A - Daily until Part B is completed.

Part B - Within the next 165 flight hours.

E. APPROVAL By delegated authority.

F. <u>TOOLING</u> N/A.

G. WEIGHT AND BALANCE Negligible change.

H. REFERENCE 750XL Maintenance Manual.

I. HOURS REQUIRED Part A - 1 Hour.

Part B - 3 Hours.

J. WARRANTY COVER Normal Warranty conditions apply.



2. ACCOMPLISHMENT INSTRUCTIONS

Part A - Daily Inspection

NOTE: The initial inspection (Steps A.1 to A.3) should be performed by a qualified and approved LAME.

- A.1) Remove the control stick boot, for both port side and starboard side control column.
- A.2) Inspect the bearing assemblies at both fork ends for security. Make sure the bearings are seated in the fork ends tightly and show no sign of slipping out.
- A.3) Re-install the control stick boot.

<u>NOTE</u>: Daily visual inspections may be performed by a qualified pilot.





FIGURE 1 REMOVAL – FLOOR COVER AND STICK BOOT (TYPICAL)

Part B - Installation - hardware

- B.1) Remove the control stick boot and cockpit floor cover (Ref. 750XL MM, Section 27-10-00, Page 401).
- B.2) Uninstall the PAL NUT and the self-locking nut. Carefully remove the bolt. Refer Figure 2. Remove existing hardware.



Page 2 of 4 Issued: 21 January 2019

PACIFICAEROSPACE

NOTE: While removing the bolt from the structure, insert a tooling pin following the trace of the bolt (tooling pin should have a diameter of 0.3", and length of

trace of the bolt (fooling pin should have a diameter of 0.3", and length of 3.50"). This procedure will ensure hardware will not drop down, and the fork

will align with the torque tube.

NOTE: The exploded views (Figures 2 and 3) are for clarification only. It is not

required to remove the bearings and bushings from the fork.

<u>CAUTION</u>: Be careful handling the bearing, as the inner part of this bearing can slip out easily.

B.3) Re-install the hardware as follows:

a) Open the inner diameter of the P/N AN970-4 washer with a 5/16" drill. (Refer WAS7-3 washer in Figure 3, refer to the attached drawing). The WAS18-1 washers may also be fabricated IAW the attached drawing.

NOTE: The Bolts P/N NAS6605D60 may be fabricated from P/N NAS6605-60 iaw PAL DWG BOL6605 (refer to the attached drawing).

b) Apply AeroShell 22 grease (or any grease product that meet MIL-PRF-81322) to the drilled surface and the inner face of the AN970 washers (See Figure 3).

NOTE 1: Ensure that the bolt thread is not contaminated by grease.

NOTE 2: Check that the teflon washers are in between the pivot and the fork before assembly.

c) Re-install all parts, according to the sequence shown in Figure 3. Torque nut to 100 - 140 lb.in, before installing the split pin.




FIGURE 3 RE INSTALLATION – HARDWARE



- B.4) A duplicate inspection is required to the work carried out above.
- B.5) Reinstall the cockpit floor cover and control stick boot (Ref. 750XL MM, Section 27-10-00, Page 401).
- B.6) Carry out the functional test (after full installation), ensure full and free movement.

3. **CERTIFICATION**

Record compliance with this Service Bulletin in the Aircraft Logbook.

The accomplishment of Part B of this Service Bulletin is a terminating action.

4. MATERIAL REQUIRED

<u>Description</u>	Part Number	Qty Required
Washer	WAS7-3 (Refer attached drawing)	4
Washer	WAS18-1 (Refer attached drawing)	4
Washer	AN960-516	2
Washer *	AN960-516L (or AN960-516)	2
Nut	MS17825-5	2
Split pin	MS24665-132	2
Bolt	NAS6605D60 OR NAS1305-60D OR PAL BOL6605D60 OR NAS6605-60 (hole drilled iaw PAL DWG BOL6605)	2
Grease	AeroShell Grease 22 (MIL- PRF-81322)	A/R
Tooling pin	-	

^{*} use as necessary to prevent thread bound

Page 4 of 4 Issued: 21 January 2019