The following Documents have been published or updated by EASA and may be of interest to you:

* AD 2013-0122 - AIRBUS: SUPERSEDED BY EASA AD 2018-0091

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2013-0122

* EAD 2015-0239-E - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2018-0090

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2015-0239-E

* **AD** 2018-0091 - AIRBUS: Fuselage – Belly Fairing and Keel Beam Side Panel Attachment Angles – Inspection / Replacement / Repair

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0091

* PAD 18-056 - AIRBUS: Exhaust – Thrust Reverser Lower Beam – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/18-056

* **AD** 2018-0090 - AIRBUS HELICOPTERS: Landing Gear – Emergency Flotation Gear Upper Fitting Attaching Screws – Inspection / Replacement / Modification

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0090

* PAD 18-055 - AIRBUS: Landing Gear – Main Landing Gear Sliding Tube – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/18-055