

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2013-0122 - AIRBUS: SUPERSEDED BY EASA AD 2018-0091

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2013-0122>

---

\* **EAD** 2015-0239-E - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2018-0090

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2015-0239-E>

---

\* **AD** 2018-0091 - AIRBUS: Fuselage – Belly Fairing and Keel Beam Side Panel Attachment Angles – Inspection / Replacement / Repair

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0091>

---

\* **PAD** 18-056 - AIRBUS: Exhaust – Thrust Reverser Lower Beam – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-056>

---

\* **AD** 2018-0090 - AIRBUS HELICOPTERS: Landing Gear – Emergency Flotation Gear Upper Fitting Attaching Screws – Inspection / Replacement / Modification

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0090>

---

\* **PAD** 18-055 - AIRBUS: Landing Gear – Main Landing Gear Sliding Tube – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-055>