

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2016-0106R1** - AIRBUS: Fuselage – Frame 35.2A - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0106R1>

* **AD 2018-0067** - ENSTROM HELICOPTER CORPORATION: SUPERSEDED BY EASA AD 2018-0286

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0067>

* **AD 2018-0286** - ENSTROM HELICOPTER CORPORATION: Main Rotor – Hydraulic Damper / Belt Tension Shaft Rod End Assembly – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0286>

* **AD CF-2018-34** - BOMBARDIER: Flight Controls – Elevator Power Control Unit Bracket Cracking

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2018-34>

* **AD 2018-0287** - AIRBUS HELICOPTERS: Rotors Flight Control – Tail Rotor Gearbox Actuating Rod – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0287>

* **AD CF-2018-35** - BELL HELICOPTER TEXTRON CANADA (BHTC): Tail Rotor Drive – Tail Rotor Gearbox – Introduction of Attachment Hardware Recurring Torque Check

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2018-35>