

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2014-0181 - PILATUS AIRCRAFT LTD: SUPERSEDED BY EASA AD 2018-0285

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2014-0181>

* **AD** 2018-0283 - AIRBUS HELICOPTERS DEUTSCHLAND: Rotors Flight Control – Main Rotor Actuator – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0283>

* **AD** 2018-0284 - AIRBUS HELICOPTERS DEUTSCHLAND: Rotors Flight Control – Main Rotor Actuator – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0284>

* **SIB** 2018-20 - Safety Information Bulletin: HELICOPTERS GUIMBAL Cabri G2 Helicopters - Main Rotor Mast, Tail Boom Fittings and Transmission Shaft – Corrosion Protection Improvement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-20>

* **AD** 2018-0285 - PILATUS AIRCRAFT LTD: Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0285>

* **PAD** 18-182 - ASI AVIATION: Electrical Power – Circuit Breaker Switches – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-182>

* **PAD** 18-183 - ASI AVIATION: Flight Controls – Rudder Control Pedal Torque Tubes – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-183>
