

The following Documents have been published or updated by EASA and may be of interest to you:

* **EAD** 2018-0261-E - LEONARDO S.p.A. HELICOPTERS: [Correction] Tail Rotor – Tail Rotor Servo Actuator – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0261-E>

* **AD** 2018-0260 - AIRBUS HELICOPTERS: Fuselage – Main Gearbox Suspension Bar Fittings and Screws – Life Limit / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0260>

* **PAD** 18-165 - AIRBUS: Flight Controls / Stabilizers – Rudder Servo Control – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-165>

* **PAD** 18-166 - AIRBUS HELICOPTERS DEUTSCHLAND: Rotors Flight Control – Main Rotor Actuator – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-166>

* **PAD** 18-167 - AIRBUS HELICOPTERS DEUTSCHLAND: Rotors Flight Control – Main Rotor Actuator – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-167>

* **SIB** CE-18-32 - Safety Information Bulletin: Textron Aviation Model 208B Aeroplanes - Engine Oil System (Airframe Furnished) - Flapper Check Valve Failure

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CE-18-32>