

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2011-0164R1** - AIRBUS HELICOPTERS: Rotors Flight Control – Tail Rotor Control Stop Screws – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2011-0164R1>

* **PAD 15-087** - AIRBUS HELICOPTERS: WITHDRAWN - EXPLANATORY STATEMENT ATTACHED

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/15-087>

* **AD 2017-0026** - AIRBUS HELICOPTERS DEUTSCHLAND: Electrical Power – Overhead Panel Shock Mounts – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0026>

* **AD US-2017-02-09** - BOEING: Fuselage - Fuselage Crown Skin Inner Surface - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2017-02-09>

* **AD 2017-0025** - LEONARDO S.p.A. HELICOPTERS: Equipment & Furnishings – Hoist – Modification / Inspection / Rotorcraft Flight Manual Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0025>
