

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 27/01/2017 and 09/02/2017.

These, and other Airworthiness Directives can be viewed at:

<https://www.casa.gov.au/airworthiness/standard-page/airworthiness-directives>

### **Rotorcraft**

#### [Airbus Helicopters \(Eurocopter\) AS 332 Series Helicopters](#)

[2017-0022](#) - Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection

#### [Airbus Helicopters \(Eurocopter\) AS 350 and EC 130 Series Helicopters](#)

[2017-0020-E](#) - Tail Rotor - Pitch Rod - Inspection

#### [Airbus Helicopters \(Eurocopter\) AS 355 Series Helicopters](#)

[2017-0020-E](#) - Tail Rotor - Pitch Rod - Inspection

#### [Leonardo Helicopters \(AgustaWestland\) AB139 and AW139 Series Helicopters](#)

[2011-0205R1 \(Correction\)](#) - Stabilizers - Tail Fin Assembly - Inspection / Replacement

[2017-0011](#) - Tail Rotor - Tail Rotor Drive Shaft - Inspection / Modification

#### [Robinson Helicopter Company R44 Series Helicopters](#)

[AD/R44/25 Amdt 2](#) - Main Rotor Blades - CANCELLED

### **Below 5700 kgs**

#### [Piper PA-31 Series Aeroplanes](#)

[2017-02-06](#) - Wiring Below Main Circuit Breaker Panel

#### [Socata \(Aerospatiale\) TBM700 Series Aeroplanes](#)

[AD/TBM 700/27 Amdt 1](#) - Elevator Control System - CANCELLED

[2017-0018](#) - Flight Controls - Aileron Control - Modification

### **Above 5700 kgs**

#### [328 Support Services Dornier 328 Series Aeroplanes](#)

[2017-0016](#) - Fuel - Fuel Line Clamps - Inspection / Replacement

#### [Airbus A330 Series Aeroplanes](#)

[2017-0021](#) - Fuselage - Cabin and Cargo Compartments Parts - Inspection / Replacement

#### [Airbus A380 Series Aeroplanes](#)

[2017-0013](#) - Wings - Flap Parts - Identification / Inspection [Wrong material]

[2015-0141R3](#) - Wings - Leading Edge Shear Cleats - Inspection / Replacement

[2017-0015](#) - Fuselage - Belly Fairing - Inspection / Repair / Replacement

#### [Boeing 717 Series Aeroplanes](#)

[2017-01-03](#) - Airworthiness Limitations

#### [Boeing 737 Series Aeroplanes](#)

[2017-02-05](#) - Skin Cracking Around aft Entry and aft Galley Doorways

[Boeing 747 Series Aeroplanes](#)

[2017-02-04](#) - Cracking of Strut Side Skin and Spring Beam Support Fitting

[Bombardier CL-600 Series Aeroplanes](#)

[CF-2017-06](#) - Rudder Controls - Yaw Damper Uncommanded Movement

[CF-2016-20R1](#) - Equipment/Furnishings - Electrical Short of Bonding Jumper causing Burnt Water Supply Line and Smoke in Cabin

[CF-2017-07](#) - Cold Weather Operations - Introduction of Low Temperature Ground Wing Anti-Ice System

**Turbine Engines**

[Rolls Royce Deutschland Turbine Engines - Spey Series](#)

[2017-0014](#) - Engine - High Pressure Compressor Stage 12 Rotor Discs - Replacement [Life Limit]

[Safran Helicopter Engines \(Turbomeca\) Turbine Engines - Arriel Series](#)

[2017-0019-E](#) - Engine Fuel & Control - Drain Valve Assembly - Inspection / Replacement

--

To update your preferences and to unsubscribe visit [this link](#)

Forward a Message to Someone [this link](#)

POWERED BY [PHPLIST](#)

Email secured by Check Point