

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2015-0212 - AIRBUS: SUPERSEDED BY EASA AD 2018-0147

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2015-0212>

* **AD** 2018-0148 - AIRBUS: Exhaust – Thrust Reverser Lower Beam – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0148>

* **AD** 2018-0147 - AIRBUS: Fuselage – Cabin and Cargo Compartments Structural Parts – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0147>

* **EAD** 2018-0120-E - LEONARDO S.p.A. HELICOPTERS: SUPERSEDED BY EASA AD 2018-0149-E

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0120-E>

* **AD** 2018-0145R1 - AIRBUS: Flight Controls – Elevators and Rudder Servocontrols – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0145R1>

* **EAD** CF-2018-18 - BELL HELICOPTER TEXTRON CANADA (BHTC): Tail Rotor Drive – Loose Tail Rotor Gearbox

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2018-18>

* **SIB** NM-18-18 - Safety Information Bulletin: Boeing 737 Aeroplanes - Equipment/Furnishings – First Observer’s Seat Cup Holder

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/NM-18-18>

* **EAD 2018-0149-E** - LEONARDO S.p.A. HELICOPTERS: Electrical Power – Electrical Cables – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0149-E>