

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD CF-2016-14R1** - BOMBARDIER: Fuselage – Excessive Tape on Floor Structure - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CF-2016-14R1>

---

\* **AD 2017-0139R1** - LEONARDO S.p.A. HELICOPTERS: Fuselage – Underbelly Tank Fuel Sump Electrical Bonding – Modification

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2017-0139R1>

---

\* **AD 2018-0145R2** - AIRBUS: Flight Controls – Elevators and Rudder Servocontrols – Replacement / Modification

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0145R2>

---

\* **AD BR-2018-07-01** - EMBRAER: Landing Gear - Pintle Pins of the Main Landing Shock Strut - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/BR-2018-07-01>

---