

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2017-0245** - AIRBUS: SUPERSEDED BY EASA AD 2018-0150

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0245>

* **AD 2018-0150** - AIRBUS: Landing Gear – Repaired Main Landing Gear Wheel Axles – Reduced Life Limit

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0150>

* **AD US-2018-06-11** - STANDARD AERO\TEXTRON AVIATION INC.: Turbocharging - Exhaust Tailpipe V-Band Coupling (Clamp) - Life Limit / Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-06-11>

* **AD 2018-0151** - AIRBUS: Flight Controls – Outboard Flap Drive Station Elements and Sensor Strut – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0151>

* **PAD 18-095** - DASSAULT AVIATION: Time Limits / Maintenance Checks – Supplementary Structural Inspection Program – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-095>

* **SIB CE-18-22** - Safety Information Bulletin: Textron Aviation (formerly Beechcraft) A36TC, B36TC, S35, V35, V35A, and V35B aeroplanes - Alternative Method of Compliance to FAA AD 2018-06-11

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CE-18-22>

* **PAD** 18-096 - AIRBUS: Nacelles / Pylons – Lower Aft Pylon Fairing Drain Pipe and U-Shapes – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/18-096>

* **AD** US-2018-13-01 - ROLLS-ROYCE CORPORATION (USA): Engine Fuel & Control - Power Turbine Governor Bearing Assembly - Removal / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/US-2018-13-01>

* **PAD** 18-097 - AIRBUS: Aircraft Flight Manual / Engine Bleed Air System – Amendment; Indicating & Recording System – Flight Warning Computer – Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/18-097>