

The following Documents have been published or updated by EASA and may be of interest to you:

\* **PAD** 18-152 - AIRBUS: Wings – Centre Section Frame 40 Forward Fitting Radius at Tension Bolt Junction – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-152>

---

\* **AD** CF-2018-29 - BOMBARDIER: Flight Controls – Elevator and Rudder Rod Ends of the Power Control Units

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CF-2018-29>

---

\* **AD** CF-2018-30 - BOMBARDIER: Stabilizers - Elevator - Spring Tab - Mass Balance Hinge Arm Fracture

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CF-2018-30>

---

\* **AD** US-2018-22-02 - INTERNATIONAL AERO ENGINES LLC: Engine - High-Pressure Compressor Front Hub - Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-22-02>

---

### **IMPORTANT NOTICE**

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section