

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2015-0141R5** - AIRBUS: Wings – Leading Edge Shear Cleats – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2015-0141R5>

* **AD 2016-0226** - AIRBUS: SUPERSEDED BY EASA AD 2018-0192

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0226>

* **AD 2017-0182** - AIRBUS: SUPERSEDED BY EASA AD 2018-0191

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0182>

* **AD 2018-0192** - AIRBUS: Aircraft Flight Manual / Engine Bleed Air System – Amendment; Indicating & Recording System – Flight Warning Computer – Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0192>

* **AD 2018-0191** - AIRBUS: Fuel – Fuel Pumps / Outboard Collector Cell Jet Pump – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0191>

IMPORTANT NOTICE

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section