

## MCAI Information Form

In support of the Civil Aviation Authority actions to address your Mandatory Continued Airworthiness Information (MCAI), please provide the information below, if not contained in the referenced service information. **Important Note:** The Director may require information considered necessary in the interests of civil aviation safety, Civil Aviation Act 1990 Section 15 refers.

Aircraft Manufacturer/Model *Pacific Aerospace Ltd / P-750 XL*

Service Bulletin/Revision/Date *PACSB/XL/105 – Issue 2 – 28/06/2018*

Number of aircraft affected, all aircraft or by S/N:

Part A – ALL 750XL aircraft up to and including S/N 220 (excluding S/N`s 214, 216, 217, 218, 219).

Part B – ALL 750XL aircraft up to and including S/N 185 (excluding S/N 177).

1. Describe the unsafe condition, AND its root cause. Include a description of how the problem could affect the safe operation of the aircraft:

*Refer to ECN 11-41001-K-L1 (attached).*

2. Provide the number and description of occurrences that prompted the mandatory service bulletin:

*Preventive action only. No instances have been reported of damage due to loss of fasteners.*

3. How was the compliance time(s) established?

*Low risk. No loss of fasteners reported.*

4. Cost of parts and/or installation man hours?

Material costs: 13 \$ / Man Hours: Part A: 1 hour / Part B: 2 hours.

5. If parts are required, are they available for all aircraft?

*Yes.*

## MCAI Information Form

In support of the Civil Aviation Authority actions to address your Mandatory Continued Airworthiness Information (MCAI), please provide the information below, if not contained in the referenced service information. **Important Note:** The Director may require information considered necessary in the interests of civil aviation safety, Civil Aviation Act 1990 Section 15 refers.

6. What category best describes the cause of the unsafe condition? Design problem, maintenance, quality control problem, unapproved parts, operational or other (specify):

*Design derived from aircraft certified prior to FAR 23.607 (a) [amdt. 23-48] becoming effective.*

7. Should a ferry flight be permitted? Yes/No?

*Yes.*

8. If this is an interim action is a terminating action available? If so, please provide a description and recommended compliance time:

*This SB is a terminating action.*

9. Other additional information:

*Refer to ECN 11-41001-K-L1 (attached).*

Form completed by: *Ricardo Correia*  
Contact phone number: *(07) 843 6144*

Date: *02/07/2018*