

**Occurrence Communication:** Oc00247-2018      **Date:** 31/Aug/2018

Page 1 of 1

**Type:** /

<b>Aircraft:</b> EMB-505	<b>Model:</b> EMB-505	<b>Serial Number:</b> 5050313
<b>Marks:</b> N361AS	<b>Operator:</b> Executive AirShare, LLC	<b>Occurrence Date:</b> 28/Aug/2018
<b>Ata:</b> 24	<b>Time:</b>	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b>		
<b>Site:</b> MC CARRAN INTL - LAS VEGAS - NV - UNITED STATES		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of precautionary engine 2 IFSD  
The flight crew reported an abnormal engine 2 vibration during flight. They elected to perform a precautionary engine 2 IFSD and divert to another airport.

Maintenance personnel identified the engine 2 starter generator as the root cause of the vibration.