

Occurrence Communication: Oc00250-2018 **Date:** 04/Sep/2018

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 LR	Serial Number: 145415
Marks: N14916	Operator: EXPRESSJET	Occurrence Date: 31/Aug/2018
Ata: 34	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: SHREVEPORT REGL - SHREVEPORT - LA - UNITED STATES		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of air return due to smoke in the cockpit
The flight crew reported smoke in the cockpit. They then returned to the departure airport. Maintenance personnel determined the cause of the smoke to be the light of the compass. The compass lighting was deactivated by pulling the circuit breaker and put on MEL.