

## EMBRAER S.A.

Oc00255-2018

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Date: 12/Sep/2018

Page 1 of 1

Т	v	p	e	2	1
-		-	_	-	

Aircraft:	Model:	Serial Number:			
EMB-145	EMB-145 LR	145501			
Marks:	Operator:	Occurence Date:			
N48901	EXPRESSJET	10/Sep/2018			
<b>Ata:</b> 72	Time:	Number of Persons Aboard: Not Available			
Aircraft Damages:					
Site: CHICAGO-O'HARE INTL - CHICAGO - IL - UNITED STATES					
Injuries: X None Light:	0 Serious: 0 Fat	t <b>al:</b> 0			

## **Occurence Description:**

Report of precautionary engine 2 IFSD during descent

The flight crew reported the "E2 OIL LOW PRESS" warning message on EICAS during descent. Following the QRH procedure, they commanded a precautionary engine 2 IFSD and proceeded to an uneventful single engine landing at destination airport.

Maintenance personnel identified an oil leakage in the engine's rear turbine bearing support (RTBS). The engine was removed and replaced.