

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication: Oc00266-2018 Date: 26/Sep/2018 Page 1 of 1

Type: /

EMB-135 KL	145631
Operator:	Occurence Date:
ENVOY	23/Sep/2018
Time:	Number of Persons Aboard: Not Available
Aircraft Damages:	
Site: KENNEDY INTL - NEW YORK - NY - UNITED STATES	
Serious: ⁰ Fatal:	0
	Operator: ENVOY Time: UNITED STATES

Occurence Description:

Report of smoke coming from the right main landing gear during landing

It was reported smoke coming from the right main landing gear during landing. Maintenance personnel found the right main landing gear inboard brake shuttle valve, bleeder valve, and hydraulic hose quick disconnect leaking. They performed corrective actions and released the aircraft to service.

Due to the event reoccurrence in the subsequent flight, they removed and replaced the right main landing gear inboard brake assembly.