

Occurrence Communication: Oc00319-2018 **Date:** 23/Nov/2018

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 XR	Serial Number: 145964
Marks: N14203	Operator: EXPRESSJET	Occurrence Date: 04/Apr/2018
Ata: 12	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of air return due to smoke in the cockpit and cabin during climb
The flight crew reported smoke in the cockpit and cabin during climb. They then elected to return to the departure airport, landing without further incident.

Maintenance personnel determined the smoke source as being de-ice fluid ingestion. They then performed air ducts decontamination. Subsequent operational checks were satisfactory and the aircraft was released for return to service.