

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00321-2018 Date: 26/Nov/2018

Page 1 of 1

Type: Other

Aircraft:	Model	:	S	erial Number:	
EMB-145	EMB-1	EMB-145 XR		145927	
Marks: N11187	Opera COMM	tor: IUTAIR		ccurence Date: B/Nov/2018	
Ata: 21	Time:	Time:		umber of Persons Aboard: ot Available	
Aircraft Damages:					
Site: NOT AVAILABLE					
Injuries: 🔀 None	Light: 0	Serious: ⁰	Fatal:	0	

Occurence Description:

Report of abnormal noise and smoke in the cockpit

The flight crew reported an abnormal noise and smoke in the cockpit flying at FL280. They then declared emergency and landed at destination airport.

Maintenance personnel found electronics compartment fan 2 not working. They then removed and replaced forward electronic compartment cooling fan 2. Subsequent operational checks were satisfactory.