

# Airworthiness Directive

## Pacific Aerospace 750XL Aircraft

---



---

Issued by the Civil Aviation Authority of New Zealand in accordance with section 72I(3A) of the Civil Aviation Act. An Airworthiness Directive (AD) contains regulatory information which is mandatory. An operator of an aircraft must not operate the aircraft unless the operator complies with every applicable AD issued by the Director in accordance with section 72I(3A) of the Civil Aviation Act. An AD is issued where the Director believes on reasonable grounds that an unsafe condition exists in an aircraft or aeronautical product.

---

### DCA/750XL/24                      Pitot Static Tube Support Clamps - Inspection

- Applicability:** Pacific Aerospace 750XL aircraft, all S/N up to and including 220.
- Requirement:** To prevent possible chafing of the pitot static tubes with the primary support at the flame arrestor intersection, accomplish the inspection and corrective actions per the Accomplishment Instructions in Pacific Aerospace Mandatory Service Bulletin (MSB) PACSB/XL/094 issue 1, dated 14 December 2017, or later approved revision.
- Compliance:** At the next 300 hour maintenance inspection, or by 28 February 2018, whichever is the sooner.
- Effective Date:** 28 December 2017
- Background:** This AD is prompted by a production inspection of installed pitot static plumbing which identified insufficient clearance between the pitot tubes and the primary support at the flame arrestor intersection. This AD with effective date 28 December 2017 mandates the inspection and corrective actions per the Accomplishment Instructions in Pacific Aerospace Mandatory Service Bulletin (MSB) PACSB/XL/094 issue 1, dated 14 December 2017, or later approved revision.

A handwritten signature in black ink, appearing to read 'Owen Olls', is positioned above the typed name and title.

Owen Olls  
*Airworthiness Specialist*  
*Delegate of the Civil Aviation Authority of New Zealand*  
21 December 2017