

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2019-0023 - LEONARDO S.p.A. HELICOPTERS: SUPERSEDED BY EASA AD 2019-0121

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0023>

* **AD** 2019-0120 - FOKKER SERVICES: Electrical Power “ Power Transfer Contactors “ Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0120>

* **EAD** 2019-0119-E - LEONARDO S.p.A. AIRCRAFT: Flight Controls “ Flap Actuator “ Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0119-E>

* **PAD** 19-098 - AIRBUS HELICOPTERS: Main Rotor Drive “ Main Gearbox Top Sensor / Main Rotor Mast Lubrication System “ Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-098>

* **AD** 2019-0121 - LEONARDO S.p.A. HELICOPTERS: Tail Rotor “ Tail Rotor Servo Actuator / Duplex Bearing “ Inspection / Check

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0121>