Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **PAD** 19-037 - AIRBUS: Electric and Electronic Common Installation – Electrical Wiring – Modification

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/19-037

* **AD** CF-2019-07 - VIKING AIR LTD: Wing – Cracking of the Wing Lower Skin at Wing Station 51 under the Drag Angle

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/CF-2019-07

* **AD** CF-2019-09 - BOMBARDIER\ROCKWELL COLLINS: Avionic System – Airplane Flight Manual Navigation System Limitations – Prohibit Editing CLIMB TO Altitudes and Use of Temperature Compensation on Flight Management System

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/CF-2019-09

* PAD 19-036 - AIRBUS: Exhaust – Thrust Reverser Lower Beam – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/19-036

* **AD** CF-2019-10 - BOMBARDIER\ROCKWELL COLLINS: Avionic System – Airplane Flight Manual Navigation System Limitations – Prohibit Editing CLIMB TO Altitudes and Use of Temperature Compensation on Flight Management System

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/CF-2019-10