

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** CF-2014-26 - AIRBUS HELICOPTERS\BELL HELICOPTER TEXTRON CANADA (BHTC)\BELLIS INVESTMENTS LTD\MD HELICOPTERS INC (MDHI): SUPERSEDED BY TCCA AD CF-2019-01

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2014-26>

* **AD** 2018-0137R1 - AIRBUS: Nacelles / Pylons – Pylon Aft Fixed Fairings – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0137R1>

* **AD** 2018-0265R1 - BRP-ROTAX GmbH & Co KG: [Correction] Engine – Exhaust Valve – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0265R1>

* **AD** 2019-0001 - AIRBUS HELICOPTERS: Doors – Sliding Door Opening Mechanism – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0001>

* **PAD** 19-002 - AIRBUS HELICOPTERS DEUTSCHLAND: Airworthiness Limitation Section – TT-Straps – Storage Life Limit

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-002>

* **PAD** 19-003 - AIRBUS: Flight Controls – Flight Control Primary Computer – Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-003>

* **PAD** 19-004 - SOLO KLEINMOTOREN GmbH: Engine – Propeller Reduction Gear Excentric Axle Bearings – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-004>

* **AD** CF-2018-36 - BOMBARDIER: Navigation – Flight Instruments – Unreliable Air Data in the Cockpit

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2018-36>

* **AD** CF-2019-01 - AIRBUS HELICOPTERS\BELL HELICOPTER TEXTRON CANADA (BHTC)\BELLIS INVESTMENTS LTD\MD HELICOPTERS INC (MDHI): Standard Practices – Helicopter External Transport System (HETS™) - Unapproved Parts, Inadequate Service Life Limits and Maintenance Requirements

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2019-01>

* **AD** CF-80-06 - VIKING AIR LTD: SUPERSEDED BY TCCA AD CF-2019-02

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-80-06>

* **AD** CF-81-07R4 - VIKING AIR LTD: SUPERSEDED BY TCCA AD CF-2019-02

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-81-07R4>

* **AD** CF-95-12 - VIKING AIR LTD: SUPERSEDED BY TCCA AD CF-2019-02

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-95-12>

* **AD** CF-2000-14 - VIKING AIR LTD: SUPERSEDED BY TCCA AD CF-2019-02

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2000-14>

* **AD** CF-2019-02 - VIKING AIR LTD: Time Limits / Maintenance Checks – Airworthiness Limitations - Implementation

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/CF-2019-02>

