

The following Documents have been published or updated by EASA and may be of interest to you:

\* **EAD 2006-0352-E** - RUAG AEROSPACE SERVICES, GMBH: SUPERSEDED BY EASA AD 2019-0307

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2006-0352-E>

---

\* **AD CF-2019-30R1** - PRATT & WHITNEY CANADA: Compressor Turbine Blade Fracture due to Non-conforming CT Vane Installation

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/CF-2019-30R1>

---

\* **AD 2019-0239R1** - XTREMEAIR GmbH: Power Plant – Engine Mount – Inspection / Placards & Markings – Aerobatics Manoeuvres Prohibited – Installation / Aircraft Flight Manual – Section Limitations – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0239R1>

---

\* **AD 2019-0307** - RUAG AEROSPACE SERVICES, GMBH: Landing Gear – Carbon Brake Assembly – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0307>

---