The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2016-0232R1 - AIRBUS HELICOPTERS: Rotor Drive(s) – Main Gear Box / Emergency Spraying System – Modification / Functional Test

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2016-0232R1

* AD 2018-0043R1 - AIRBUS: Power Plant – Rear Engine Mount Assembly – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2018-0043R1

* **AD** 2018-0213R1 - AIRBUS: SUPERSEDED BY EASA AD 2019-0301

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2018-0213R1

* **AD** 2019-0300 - WSK PZL - SWIDNIK S.A.: Main Rotor — Lower and Upper Torque Scissors — Inspection

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0300

* **SIB** CE-19-21 - Safety Information Bulletin: Air Tractor, Inc., Models AT-602, AT-802, and AT-802A Airplanes - Flap Motor Mounting Studs

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/CE-19-21

* **PAD** 19-212 - CFM INTERNATIONAL: Engine – Rotating Air High Pressure Turbine Front Seal – Replacement

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/19-212

* **AD** 2019-0301 - AIRBUS: Flight Controls — Aileron and Elevator Electro-Hydrostatic Actuators — Modification Aircraft Flight Manual — Amendment

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0301

^{*} **EAD** ISR-I-53-2019-12-6 - BOEING\ISRAEL AIRCRAFT INDUSTRIES: Loading Restrictions due to 9G Barrier Manufacturing Non-Compliance

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/ISR-I-53-2019-12-6