The following Documents have been published or updated by EASA and may be of interest to you:

* AD 2011-0159 - FOKKER SERVICES: SUPERSEDED BY EASA AD 2019-0224

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2011-0159

* AD 2017-0163 - FOKKER SERVICES: SUPERSEDED BY EASA AD 2019-0224

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2017-0163

* **AD** 2019-0099R2 - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Engine – High Pressure Turbine Blades – Inspection / De-Pairing Limitation

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0099R2

* AD 2019-0223 - AIRBUS: Wings — Outer Rear Spar — Inspection

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0223

* AD 2019-0222 - AIRBUS: Fuselage – Belly Fairing Torsion Box – Modification

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0222

* AD 2019-0224 - FOKKER SERVICES: Landing Gear – Main Landing Gear / Piston – Inspection / Replacement / Modification

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0224

* PAD 19-165 - AIRBUS HELICOPTERS: Landing Gear – Main Landing Gear – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/19-165

* AD US-2019-16-05 - BOEING: Equipment / Furnishings - Flight Crew Seats - Inspection

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/US-2019-16-05