EASA AD No.: 2019-0263



Airworthiness Directive

AD No.: 2019-0263

Issued: 22 October 2019

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name: Type/Model designation(s):

SAAB AB SAAB 2000 aeroplanes

Effective Date: 05 November 2019

TCDS Number(s): EASA.A.069

Foreign AD: Not applicable

Supersedure: None

ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

Manufacturer(s):

SAAB AB (SAAB)

Applicability:

SAAB 2000 aeroplanes, all serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The ALM: SAAB 2000 Airworthiness Limitation Manual (ALM) Revision 1.

The AMP: The approved Aircraft Maintenance Programme (AMP) on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane. For affected SAAB 2000 aeroplanes registered in Europe, compliance with the approved AMP is required by Commission Regulation (EU) <u>1321/2014</u>, Part M.A.301, paragraph 3.

New and/or more restrictive tasks: This includes all tasks and limitations that are new or for which a threshold and/or interval was reduced, which were introduced into the ALM (as defined in this AD) since the previous ALM Revision that is currently incorporated in the AMP.



EASA AD No.: 2019-0263

Reason:

The airworthiness limitations and/or certification maintenance instructions for SAAB 2000 aeroplanes, which are approved by EASA, are currently defined and published in the SAAB 2000 ALM. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

Recently, SAAB issued SAAB 2000 ALM Revision 1, which contains new and/or more restrictive tasks. Main changes compared to the ALM at original issue are the addition of safe life tables and revised life limitations of MLG parts, the addition of a safe life parts table in the Structural Limitation Items, and the implementation of tasks related to the Corrosion Prevention and Control Programme.

For the reason described above, this AD requires accomplishment of the actions specified in the ALM, as defined in this AD.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Maintenance Tasks and Replacement of Life Limited Parts:

- (1) From the effective date of this AD, accomplish the following actions, as specified in the ALM, as applicable, depending on aeroplane configuration:
 - (1.1) Replace each component before exceeding the applicable life limit, and
 - (1.2) Within the thresholds and intervals, accomplish all applicable maintenance tasks.

Corrective Action(s):

(2) In case of finding discrepancies (as defined in the ALM) during accomplishment of any task as required by paragraph (1) of this AD, within the compliance time specified in the ALM, accomplish the applicable corrective action(s) in accordance with the applicable SAAB maintenance documentation. If no compliance time is identified in the ALM, accomplish the applicable corrective action(s) before next flight. If a detected discrepancy is not identified in the ALM, before next flight, contact SAAB for approved instructions and accomplish those instructions accordingly.

AMP Revision:

(3) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the limitations, tasks and associated thresholds and intervals described in the ALM, as applicable, depending on aeroplane configuration.

Credit:

(4) If, before the effective date of this AD, the AMP has been revised to incorporate the maintenance tasks and life limitations as specified in SAAB 2000 ALM at original issue, that action ensures the continued accomplishment of those tasks and limitations.



EASA AD No.: 2019-0263

Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and/or more restrictive tasks and limitations as specified in the ALM, as applicable, depending on aeroplane configuration, within the compliance times as specified in the ALM to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and/or more restrictive tasks and limitations, as specified in the ALM, as applicable, depending on aeroplane configuration, into the AMP to comply with paragraph (3) of this AD.

Recording AD Compliance:

(5) When the AMP of an aeroplane has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures continued accomplishment of the tasks as required by paragraphs (1) and (2) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

Ref. Publications:

SAAB 2000 ALM Revision 1 dated 01 July 2019.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

- 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
- 2. This AD was posted on 20 September 2019 as PAD 19-174 for consultation until 18 October 2019. No comments were received during the consultation period.
- Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
- 4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the EU aviation safety reporting system.
- 5. For any question concerning the technical content of the requirements in this AD, please contact: Saab AB, Support and Services, SE-581 88 Linköping, Sweden, E-mail: Saab2000.techsupport@saabgroup.com.

