

## EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00001-2019 Date: 04/Jan/2019

Page 1 of 1

## **Type: Major Event**

Aircraft:	Model:	Serial Number:
EMB-505	EMB-505	5050203
Marks:	Operator:	Occurence Date:
CS-PHA	NETJETS EUROPE	22/Dec/2018
<b>Ata:</b> 24	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: GIARMATA - TIMISOARA - ROMANIA		
Injuries: X None Light:	0 Serious: 0 Fa	tal: <sup>0</sup>

## **Occurence Description:**

Report of precautionary engine 1 IFSD due to vibration caused by starter generator failure The flight crew reported engine 1 vibration due to starter generator failure. They followed the QRH procedure and commanded a precautionary engine 1 IFSD.

Maintenance personnel removed and replaced the engine 1 starter generator. The aircraft was then returned to service with no further issues.