

Occurrence Communication: Oc00151-2019 **Date:** 03/May/2019

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 XR	Serial Number: 145924
Marks: N14186	Operator: COMMUTAIR	Occurrence Date: 23/Apr/2019
Ata: 78	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of engine 1 exhaust cone found to be missing
 Maintenance personnel reported a missing engine 1 exhaust cone during a pre-flight walkaround. There was no associated event with the finding and no reports of injury or other damage.

The engine 1 was removed and replaced and the aircraft was returned to service.

ADDITIONAL INFORMATION:

Service Engineering attended the engine teardown and reported that 3 of the 12 bolts that attached the exhaust cone to the rear turbine bearing support (RTBS) were missing. The RTBS and exhaust cone are being returned to the manufacturer for further analysis.