

Occurrence Communication: Oc00153-2019 **Date:** 06/May/2019

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-135 KL	Serial Number: 145506
Marks: N807AE	Operator: ENVOY	Occurrence Date: 02/May/2019
Ata: 21	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: SYRACUSE HANCOCK INTL - SYRACUSE - NY - UNITED STATES		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of smoke in the cockpit.
The flight crew reported smoke in the cockpit during flight.
Maintenance personnel removed and replaced duct temperature sensor #1 and #2 O-Ring. They also noticed failure of the Air Cycle Machine bearing, and this was the cause of odor event. Removed and replaced pack #1 Air Cycle Machine.