

**Occurrence Communication:** Oc00156-2019      **Date:** 07/May/2019

Page 1 of 1

**Type:** /

<b>Aircraft:</b> EMB-145	<b>Model:</b> EMB-145 XR	<b>Serial Number:</b> 145719
<b>Marks:</b> N12136	<b>Operator:</b> TRANS STATES	<b>Occurrence Date:</b> 02/Jul/2018
<b>Ata:</b> 24	<b>Time:</b>	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b>		
<b>Site:</b> NOT AVAILABLE		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of precautionary engine 1 IFSD due to low oil pressure indication  
The flight crew reported the engine 1 oil pressure indication dropped during cruise. They then elected to perform a precautionary engine 1 shutdown. An uneventful single engine landing was performed.

Maintenance personnel removed and replaced the generator 1.