

## EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00166-2019 Date: 13/May/2019

Page 1 of 1

Type: /

Aircraft:	Model:	Serial Number:
EMB-145	EMB-145 XR	145664
<b>Marks:</b> N18114	Operator: TRANS STATES	Occurence Date: 07/May/2019
<b>Ata:</b> 72	<b>Time:</b> 5:30 PM	Number of Persons Aboard: 50
Aircraft Damages:		
Site: GREATER PEORIA REG	GL - PEORIA - IL - UNITED STATES	
Injuries: 🔀 None	Light: <sup>0</sup> Serious: <sup>0</sup>	Fatal: <sup>0</sup>

## **Occurence Description:**

Report of precautionary engine 2 IFSD during approach

The flight crew reported a precautionary engine 2 IFSD during approach due to a low oil pressure indication. An uneventful single-engine landing was performed.

Maintenance personnel found the retaining ring for the Air Turbine Starter (ATS) seal not properly seated in the groove when the ATS was removed. The garlock seal and the retaining ring were removed and replaced and the aircraft was returned to service.

ADDITIONAL INFORMATION:

The Air Turbine Starter (ATS) magnetic carbon seal was changed prior to the event flight.