

**Occurrence Communication:** Oc00180-2019      **Date:** 28/May/2019

Page 1 of 1

**Type:** /

|   |                             |   |
|---|-----------------------------|---|
| <b>Aircraft:</b><br>EMB-145   | <b>Model:</b><br>EMB-145 LR | <b>Serial Number:</b><br>145899                   |
| <b>Marks:</b><br>N909AE   | <b>Operator:</b><br>ENVOY   | <b>Occurrence Date:</b><br>23/May/2019            |
| <b>Ata:</b> 32  | <b>Time:</b>                | <b>Number of Persons Aboard:</b><br>Not Available |
| <b>Aircraft Damages:</b>  |                             |   |
| <b>Site:</b><br>DALLAS-FT WORTH INTL - DALLAS-FT WORTH - TX - UNITED STATES                                 |                             |   |
| <b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0 |                             |   |

**Occurrence Description:**

Report of smoke coming from the number #2 brake during landing  
It was reported smoke coming from the number #2 brake during landing. Maintenance personnel found fluid leakage on the number #2 brake. They replaced #2 Brake IAW W/C 32-600-14. Subsequent operational and leak check were performed satisfactory.