

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication: Oc00260-2019 Date: 01/Jul/2019 Page 1 of 1

Type: Major Event

Aircraft:	Model:	Serial Number:
EMB-505	EMB-505	50500309
Marks: N386QS	Operator: NETJETS SALES, INC	Occurence Date: 16/Jun/2019
Ata : 29	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: PITTSBURGH INTL - PITTSBURGH - PA - UNITED STATES		
Injuries: X None Light:	0 Serious: 0 Fatal	. 0

Occurence Description:

Report of hydraulic system fault followed by uncommanded engine 1 IFSD

The flight crew reported "HYD SYS FAULT" followed by "ENG NO DISPATCH" advisory messages on EICAS around flight level 350. Descending through the flight level 240, they faced an uncommanded engine 1 IFSD. The flight crew followed the QRH procedure and unsuccessfully tried to restart the engine 1. They then proceeded to the destination airport where an uneventful single engine landing was performed.

The technicians found the spline which connects the hydraulic engine driven pump (EDP) to the engine 1 gearbox damaged. The EDP 1 was removed and replaced. The aircraft owner and the engine manufacturer also decided to remove and replace the engine 1.

ADDITIONAL INFORMATION:

The engine 1 FMU was also removed and replaced during the troubleshooting.