

**Occurrence Communication:** Oc00262-2019      **Date:** 01/Jul/2019

Page 1 of 1

**Type:** Other

<b>Aircraft:</b> EMB-145	<b>Model:</b> EMB-135 LR	<b>Serial Number:</b> 145489
<b>Marks:</b> N805AE	<b>Operator:</b> ENVOY	<b>Occurrence Date:</b> 10/Sep/2018
<b>Ata:</b> 53	<b>Time:</b>	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b>		
<b>Site:</b> NOT AVAILABLE		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of cockpit LH frame 10 found cracked at upper end during inspection  
LT FRAME 10 CRACKED AT UPPER END-C/A-REMOVED AND REPLACED LT FRAME 10 IAW SRM 51-40-02