

**Occurrence Communication:** Oc00480-2019      **Date:** 08/Nov/2019

Page 1 of 1

**Type:** /

<b>Aircraft:</b> EMB-145	<b>Model:</b> EMB-145 XR	<b>Serial Number:</b> 145683
<b>Marks:</b> N11121	<b>Operator:</b> TRANS STATES	<b>Occurrence Date:</b> 08/Jun/2019
<b>Ata:</b> 21	<b>Time:</b>	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b>		
<b>Site:</b> NOT AVAILABLE		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of smoke in the cabin during climb  
The flight crew reported smoke in the cabin during climb. The smoke intensified during landing.

Maintenance personnel inspected the air cycle machines (ACM) and found a drain loose. Subsequent operational checks were satisfactory.