

## EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00495-2019 Date: 25/Nov/2019

Page 1 of 1

| Т | ype: | 1 |
|---|------|---|
|   |      |   |

| Aircraft:               |        | Model:                       |                      |        | Serial Number:                             |
|-------------------------|--------|------------------------------|----------------------|--------|--|
| EMB-145                 |        | EMB-145 XF                   | २                    |        | 145878                                     |
| <b>Marks:</b><br>N12175 |        | <b>Operator:</b><br>COMMUTAI | R                    |        | <b>Occurence Date:</b><br>20/Nov/2019      |
| <b>Ata:</b> 21          |        | Time:                        |                      |        | Number of Persons Aboard:<br>Not Available |
| Aircraft Damages:       |        |                              |                      |        |  |
| Site:<br>NOT AVAILABLE  |        |                              |                      |        |  |
| Injuries: X None I      | Light: | 0 <b>s</b>                   | erious: <sup>0</sup> | Fatal: | 0  |
| Occurence Description:  |        |                              |                      |        |  |

Report of smoke in the cabin and cockpit during takeoff

The flight crew reported smoke in the cabin and cockpit immediately after takeoff. They then, returned to the airport of origin. An uneventful landing was performed.

Maintenance personnel removed and replaced the ACM 1 (air cycle machine). Subsequent operational checks were satisfactory.