

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD F-2003-366R1** - DAHER AEROSPACE: SUPERSEDED BY EASA AD 2019-0070

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/F-2003-366R1>

* **AD 2017-0191R2** - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2019-0074

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0191R2>

* **AD 2019-0069** - AIRBUS: Equipment / Furnishings – Overhead Stowage Compartments – Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0069>

* **AD 2018-0097** - AIRBUS: SUPERSEDED BY EASA AD 2019-0072

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0097>

* **AD 2018-0212R1** - AIRBUS: Powerplant – Engine Mount Titanium Crossbeam – Replacement [Life Limitation]

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0212R1>

* **AD 2019-0071** - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Engine – Low Pressure Turbine Rear Support Seal Panel – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0071>

* **AD 2019-0070** - DAHER AEROSPACE: Stabilizers – Vertical Stabilizer Attachment Fittings – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0070>

* **AD** 2019-0072 - AIRBUS: Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 2 – Damage Tolerant Airworthiness Limitation Items – Implementation

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0072>

* **AD** 2019-0074 - AIRBUS HELICOPTERS: Main Rotor – Rotating Swashplate Yokes – Inspection / Rework / Service Life Limit

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0074>

* **AD** 2019-0073 - LEONARDO S.p.A. HELICOPTERS: Tail Rotor – Full Ice Protection System Tail Rotor Blades – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0073>

* **PAD** 19-048 - FOKKER SERVICES: Equipment / Furnishings – Lavatory Waste Bins / Fire Extinguishers – Inspection / Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-048>

* **PAD** 19-049 - AIRBUS: Aircraft Flight Manual – Landing Distance Determination Procedure – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-049>

* **AD** US-2019-06-06 - INTERNATIONAL AERO ENGINES AG: Engine - Diffuser Case - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2019-06-06>

* **AD** RU-2017-322-05 - SUKHOI CIVIL AIRCRAFT, JSC: NOT ADOPTED - EASA DECISION ATTACHED

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/RU-2017-322-05>