

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** CF-2014-26 - AIRBUS HELICOPTERS\BELL HELICOPTER TEXTRON CANADA (BHTC)\BELLIS INVESTMENTS LTD\MD HELICOPTERS INC (MDHI):  
SUPERSEDED BY TCCA AD CF-2019-01

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CF-2014-26>

---

\* **AD** 2017-0183 - AIRBUS: SUPERSEDED BY EASA AD 2019-0002

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2017-0183>

---

\* **CZIB** CZIB-2018-01R2 - Conflict Zone Information Bulletin: Airspace of Saudi Arabia – Jeddah Flight Information Region - Valid until 11 July 2019

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CZIB-2018-01R2>

---

\* **CZIB** CZIB-2018-02R2 - Conflict Zone Information Bulletin: Airspace of Pakistan – Karachi and Lahore Flight Information Regions - Valid until 11 July 2019

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CZIB-2018-02R2>

---

\* **AD** 2018-0137R1 - AIRBUS: Nacelles / Pylons – Pylon Aft Fixed Fairings – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0137R1>

---

\* **AD** 2018-0276R1 - AIRBUS: Fuselage – Structural Parts / Joints – Modification / Reinforcement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0276R1>

---

\* **AD** 2019-0004 - APPLIANCES: THALES AVS FRANCE SAS - Global Navigation Satellite System – Operational Limitations

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2019-0004>

---

\* **PAD** 18-160R1 - CFM INTERNATIONAL: Engine – Fan Blades – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-160R1>

---

\* **AD** US-2018-23-12 - APPLIANCES: [Correction] ZODIAC AERO EVACUATION SYSTEMS - Fusible Plugs - Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-23-12>

---

\* **AD** 2018-0265R1 - BRP-ROTAX GmbH & Co KG: [Correction] Engine – Exhaust Valve – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0265R1>

---

\* **AD** 2019-0002 - AIRBUS: Nacelles / Pylons – Inboard and Outboard Pylon Drain System – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2019-0002>

---

\* **AD** 2019-0001 - AIRBUS HELICOPTERS: Doors – Sliding Door Opening Mechanism – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2019-0001>

---

\* **PAD** 19-002 - AIRBUS HELICOPTERS DEUTSCHLAND: Airworthiness Limitation Section – TT-Straps – Storage Life Limit

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/19-002>

---

\* **PAD** 19-003 - AIRBUS: Flight Controls – Flight Control Primary Computer – Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/19-003>

---

\* **PAD** 19-004 - SOLO KLEINMOTOREN GmbH: Engine – Propeller Reduction Gear Excentric Axle Bearings – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/19-004>

---

\* **AD** CF-2018-36 - BOMBARDIER: Navigation – Flight Instruments – Unreliable Air Data in the Cockpit

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CF-2018-36>

---

\* **AD** CF-2019-01 - AIRBUS HELICOPTERS\BELL HELICOPTER TEXTRON CANADA (BHTC)\BELLIS INVESTMENTS LTD\MD HELICOPTERS INC (MDHI): Standard Practices – Helicopter External Transport System (HETS™) - Unapproved Parts, Inadequate Service Life Limits and Maintenance Requirements

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CF-2019-01>

---

\* **AD** CF-2019-02 - VIKING AIR LTD: Time Limits / Maintenance Checks – Airworthiness Limitations - Implementation

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CF-2019-02>

---

\* **AD** US-2018-22-07 - ENGINE ALLIANCE LLC: Engine - High Pressure Compressor Stages 2-5 Spool - Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-22-07>

---

\* **AD** US-2018-26-03 - BOEING: Equipment / Furnishings - IPECO 3A090 and 3A258 Flight Crew Seats - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-26-03>

---

\* **AD** US-2018-26-06 - BOEING: Doors - Main Landing Gear Center Door Assemblies - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-26-06>

---

\* **AD** US-2018-26-05 - BOEING: Fuel - Motor-Operated Valve Actuators / Maintenance or Inspection Program - Inspection / Replacement / Revision

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-26-05>

---

\* **PAD** 19-005 - AIRBUS HELICOPTERS: Tail Rotor – Blades – Life Limit / Re-identification

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/19-005>

---

\* **AD** 2019-0003 - AIRBUS HELICOPTERS: Rotor Drive – Main Gearbox Top Sensor – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2019-0003>

---

\* **SIB** NM-18-33 - Safety Information Bulletin: Boeing 717, 737, 747, 757, 767, 787, MD-11 and MD-90 Aeroplanes - Fuel Control Switch Locking

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/NM-18-33>