

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2019-0310R1** - AIRBUS: Flight Controls – Rudder Electrical Backup Hydraulic Actuator Solenoid Valves – Replacement / Master Minimum Equipment List – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/2019-0310R1>

* **EAD 2020-0020-E** - AIRBUS: SUPERSEDED BY EASA AD 2020-0090

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/2020-0020-E>

* **PAD 20-064** - AIRBUS: Equipment / Furnishings – Light Cover / Oxygen Container Gap Seal – Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/20-064>

* **AD US-2020-08-10** - ROBINSON HELICOPTER COMPANY: Tail Rotor - Tail Rotor Blades - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/US-2020-08-10>

* **AD 2020-0090** - AIRBUS: Indicating / Recording Systems – Integrated Control Panels – Modification; Airplane Flight Manual – Abnormal / Normal Procedures Sections – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/2020-0090>