

The following Documents have been published or updated by EASA and may be of interest to you:

* **PAD** 20-060 - AIRBUS HELICOPTERS DEUTSCHLAND: Rotors Flight Control – Tail Rotor Control System – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/20-060>

* **AD** CF-2020-08 - BOMBARDIER: Ice and Rain Protection – Wing Anti-Ice System – Introduction of Safe Life Limit for Pneumatic Telescopic Duct

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/CF-2020-08>

* **SIB** NE-20-05 - Safety Information Bulletin: Continental Aerospace Technologies Reciprocating Aviation Gasoline Engines - Powerplant – Engine Camshaft Gear Tooth Fracture

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/NE-20-05>