

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2020-0077** - AIRBUS: Flight Controls – Stop Rudder Input Warning Device – Installation / Activation

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2020-0077>

* **AD 2019-0267R1** - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2020-0078

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0267R1>

* **SD SD-2020-01** - Safety Directives: Operational measures to prevent the spread of Coronavirus `SARS-CoV-2` infection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/SD-2020-01>

* **SD SD-2020-02** - Safety Directives: Operational measures to prevent the spread of Coronavirus `SARS-CoV-2` infection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/SD-2020-02>

* **AD 2020-0078** - AIRBUS HELICOPTERS: Tail Rotor – Double Bearing – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2020-0078>
