

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD 2018-0251** - CFM INTERNATIONAL: SUPERSEDED BY EASA AD 2020-0055

TO see the details OF this Publication, please click OR copy the following: URL:  
<https://ad.easa.europa.eu/ad/2018-0251>

---

\* **AD 2019-0137** - CFM INTERNATIONAL: SUPERSEDED BY EASA AD 2020-0055

TO see the details OF this Publication, please click OR copy the following: URL:  
<https://ad.easa.europa.eu/ad/2019-0137>

---

\* **AD 2020-0055** - CFM INTERNATIONAL: Time Limits / Maintenance Checks – Airworthiness Limitations Section – Implementation

TO see the details OF this Publication, please click OR copy the following: URL:  
<https://ad.easa.europa.eu/ad/2020-0055>

---

\* **AD 2020-0054** - AIRBUS: Flight Controls – Spoiler Servo Control / Hydraulic Locking Function – Operational Test

TO see the details OF this Publication, please click OR copy the following: URL:  
<https://ad.easa.europa.eu/ad/2020-0054>

---

\* **AD 2020-0050** - AIRBUS: [Correction] Fuselage – Main Deck Cargo Crossbeams – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:  
<https://ad.easa.europa.eu/ad/2020-0050>

---

\* **SIB SW-20-01** - Safety Information Bulletin: Robinson R44 and R66 Helicopters - Electrical Power System - Battery Electrolyte Leakage

TO see the details OF this Publication, please click OR copy the following: URL:  
<https://ad.easa.europa.eu/ad/SW-20-01>