The following Documents have been published or updated by EASA and may be of interest to you:

* AD 2020-0060 - AIRBUS: Exhaust – Pressure Relief Latch Access Doors – Modification

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2020-0060

* **SD** SD-2020-01 - Safety Directives: Operational measures to prevent the spread of Coronavirus `SARS-CoV-2` infection

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/SD-2020-01

* **SD** SD-2020-02 - Safety Directives: Operational measures to prevent the spread of Coronavirus `SARS-CoV-2` infection

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/SD-2020-02

* SIB 2020-04 - Safety Information Bulletin: Lithium Batteries used in Emergency Locator Transmitters

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2020-04

* **AD** CF-2020-04 - AIRBUS CANADA LP: Fuel — Accumulation of Electrostatic Charge Inside the Fuel Tank During Refueling

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/CF-2020-04

* **AD** CF-2020-06 - DE HAVILLAND AIRCRAFT OF CANADA LTD.: Standard Practices/Structures – Introduction of Barrel Nut Inspections

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/CF-2020-06

* **PAD** 20-053 - AIRBUS HELICOPTERS: Doors – Side Stairway Door Locking Safety Mechanism – Inspection / Reconditioning / Modification

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/20-053